DEKRA

CONDITION REPORT

Report No:
2017309718
DATE
09/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	09/10/2026		
Inspection Date	09/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	SUZUKI	Registration Number	MY69JRGP
Model	CIAZ 1.5 GL [2023-2026]	Register Number	
VIN	MA3AVC71S00509636	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	
Color	BLUE	Power / Displacement	
Year Model	2024	Paint Finish	TWO COAT METALLIC
Km Reading	57,169 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3AVC71S00509636

DEKRA

CONDITION REPORT

Report No:
2017309718
DATE
09/10/2026



Damage	Repair Way
Headlight Left Damaged	Replace
Headlight Right Damaged	Replace
Front Bumper Damaged	Repair
Grill Broken	Replace
Bonnet Damaged	Replace
Bonnet slam plate (Shock tower/ Inner tray) Damaged	Replace
A • Pillar Left Damaged	Repair
A • Pillar Right Damaged	Repair
Front Fender Left Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Residual Traces of Repair	Repair
Rear bumper Residual Traces of Repair	Repair
Radiator Cradle Damaged	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.84	2.74	-	
Rear	1.69	1.65	-	
Emergency / Parking	1.17	1.29	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65R15	88H	Goodyear	Assurance	V	1924	2 mm
Front Right	185/65R15	88H	Goodyear	Assurance	V	1924	1 mm
Rear Left	185/65R15	88H	Goodyear	Assurance	V	1924	2 mm
Rear Right	185/65R15	88H	Goodyear	Assurance	V	1924	2 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3AVC71S00509636

DEKRA

CONDITION REPORT

Report No:
2017309718
DATE
09/10/2026

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO AGE AND MILEAGE OF VEHICLE NORMAL WEAR AND TEAR ON INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Signs of impact damage to front of vehicle. Signs of impact damage to rear of vehicle. Poor alignment to somebody panels. Repair work done to vehicle below standard. Vehicle body in poor condition. boot does not open.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3AVC71S00509636

DEKRA

CONDITION REPORT

Report No:
2017309718
DATE
09/10/2026



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



Manual.



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3AVC71S00509636

DEKRA

CONDITION REPORT

Report No:
2017309718
DATE
09/10/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3AVC71S00509636

DEKRA

CONDITION REPORT

Report No:
2017309718
DATE
09/10/2026




90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3AVC71S00509636


DEKRA

CONDITION REPORT


Report No:
2017309718
DATE
09/10/2026



VIN PLATE OR STICKER



ADDITIONAL 3



ADDITIONAL 4



ENGINE 1



Water level



Headlight Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3AVC71S00509636

DEKRA

CONDITION REPORT

Report No:
2017309718
DATE
09/10/2026




Headlight Right



Bonnet slam plate (Shock tower/ Inner tray)



Front Bumper



Front Bumper



Bonnet



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3AVC71S00509636


DEKRA

CONDITION REPORT

Report No:
2017309718
DATE
09/10/2026



Grill


Front Fender Left


Door Front Left


Door Rear Left



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3AVC71S00509636

DEKRA

CONDITION REPORT

Report No:
2017309718
DATE
09/10/2026



Boot Lid / Hatch door



Door Rear Right




Door Front Right



A • Pillar Right



A • Pillar Left



Radiator Cradle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3AVC71S00509636