DEKRA

CONDITION REPORT

Report No:
2017314567
DATE
20/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	20/10/2026		
Inspection Date	20/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	FORD	Registration Number	KKC804NW
Model	FIGO 1.5 AMBIENTE 5-DR [2018-2021]	Register Number	
VIN	MAJGXXMTKGKK75801	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	28/02/2027
Color	WHITE	Power / Displacement	
Year Model	2019	Paint Finish	ONE COAT UNI
Km Reading	119,068 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGKK75801

DEKRA

CONDITION REPORT

Report No:
2017314567
DATE
20/10/2026





Damage	Repair Way
Fan Belt Damaged	Replace
Air conditioner pipes Damaged	Replace
Bonnet safety caps Damaged	Replace
Bonnet hinges Damaged	Repair
Headlight Left Scratched	Replace
Headlight Right Damaged	Replace
Door Sealing Rubber Rear Left Defective	Repair
Door Sealing Rubber Rear Right Defective	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Bonnet slam plate (Shock tower/ Inner tray) Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Rear bumper Damaged	Repair
Sill Panel Right Damaged	Repair
Rocker Panel Left Dented	Repair
Windscreen Chipped	Repair
Control Arm(s) Front Axle Left Damaged	Replace
Tyre Front Left Smooth	Replace
Tyre Rear Right Damaged	Replace
Spare Tyre Damaged	Replace
Chassis Dented	Repair
Engine mountings Damaged	Replace
Belly plates Damaged	Repair
Gearbox Mountings Cracked	Replace
Gearbox Oil Sweat	Repair
CV Joint(s) Front Left (inner/outer) Damaged	Replace
CV Joint(s) Front Right (inner/outer) Damaged	Replace
Radiator Cradle Damaged	Replace
Engine Noise Excessive	Repair
Chasis leg extension	damaged
Airbag warning light illuminated	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.4	2.2	-	
Rear	1.5	1.5	-	
Emergency / Parking	0.8	0.8	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGKK75801

DEKRA

CONDITION REPORT

Report No:
2017314567
DATE
20/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	175/65R14	82H	apollo	Alnac	V	0619	1 mm
Front Right	175/65R14	82T	Sumitomo	HTR t5	V	4223	4 mm
Rear Left	175/65R14	82H	GREMAX	Capturar cf1	V	4225	4 mm
Rear Right	175/65R14	82T	Annaite	AN600	V	4323	1 mm
Spare	175/65R14	82T	Anna	Temporary	V	0000	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	POWERTRAIN CONTROL MODULE	P115E:00-28	THROTTLE ACTUATOR CONTROL THROTTLE BODY AIR	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.POOR REPAIR TRACES OF REPAIR ON BODY PANELS / STONE CHIPS AND SPRAY WORK ON BODY PANELS / SIGNS OF IMPACT DAMAGE TO FRONT OF VEHICLE / RESIDUAL TRACES POOR REPAIR

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGKK75801

DEKRA

CONDITION REPORT

Report No:
2017314567
DATE
20/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGKK75801

DEKRA

CONDITION REPORT

Report No:
2017314567
DATE
20/10/2026



INTERIOR (FRONT DRIVER DOOR)



Manual



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGKK75801

DEKRA

CONDITION REPORT


Report No:
2017314567
DATE
20/10/2026



ENGINE 1



ENGINE 2




CHASSIS



REAR



Oil cap and dipstick



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGKK75801

DEKRA

CONDITION REPORT


Report No:
2017314567
DATE
20/10/2026



LR TYRE TREAD




RR TYRE TREAD




RF TYRE TREAD



Sparewheel



Brake Test



Diagnostic Report page 1


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGKK75801

DEKRA

CONDITION REPORT

Report No:
2017314567
DATE
20/10/2026



Diagnostic Report page 2



Door Sealing Rubber Rear Left




Door Sealing Rubber Rear Right



Front Bumper



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGKK75801


DEKRA

CONDITION REPORT


Report No:
2017314567
DATE
20/10/2026



Bonnet




Front Fender Left



Front Fender Right



Rear Fender Left



Rear Fender Right



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGKK75801

DEKRA

CONDITION REPORT

Report No:
2017314567
DATE
20/10/2026



Door Rear Left



Door Rear Left



Door Front Right



Door Front Right



Door Rear Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGKK75801

DEKRA

CONDITION REPORT

Report No:
2017314567
DATE
20/10/2026



Water level



Bonnet hinges



Bonnet hinges



Rear bumper



Rear bumper



Rear bumper


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGKK75801

DEKRA

CONDITION REPORT

Report No:
2017314567
DATE
20/10/2026



Engine mountings



Radiator Cradle



Radiator Cradle



Radiator Cradle



Belly plates



Tyre Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGKK75801


DEKRA

CONDITION REPORT

Report No:
2017314567
DATE
20/10/2026



Tyre Rear Right



Tyre Front Left



Rear bumper



Gearbox Mountings



CV Joint(s) Front Left (inner/outer)



CV Joint(s) Front Right (inner/outer)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGKK75801

DEKRA

CONDITION REPORT


Report No:
2017314567
DATE
20/10/2026



Fan Belt



Gearbox



Control Arm(s) Front Axle Left



Chassis



Chassis



Air conditioner pipes


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGKK75801

DEKRA

CONDITION REPORT

Report No:
2017314567
DATE
20/10/2026



Air conditioner pipes



Air conditioner pipes



Sill Panel Right



Rocker Panel Left



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGKK75801

DEKRA

CONDITION REPORT

Report No:
2017314567
DATE
20/10/2026



Headlight Right



Headlight Right



Bonnet slam plate (Shock tower/ Inner tray)



Bonnet slam plate (Shock tower/ Inner tray)



Bonnet safety caps



Bonnet safety caps

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGKK75801

DEKRA

CONDITION REPORT

Report No:
2017314567
DATE
20/10/2026



Headlight Left



Windscreen



Windscreen



Spare Tyre

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGKK75801