DEKRA

CONDITION REPORT

Report No:
2017316250
DATE
23/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	23/10/2026		
Inspection Date	23/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	HYUNDAI	Registration Number	KY26NHGP
Model	GRAND I10 1.0 MOTION 5-DR [2020-2024]	Register Number	
VIN	MALB251ALPM367854	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	28/02/2026
Color	RED	Power / Displacement	
Year Model	2022	Paint Finish	TWO COAT UNI
Km Reading	81,680 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALPM367854

DEKRA

CONDITION REPORT

Report No:
2017316250
DATE
23/10/2026





Damage	Repair Way
Engine Oil Sweat	Repair
Headlight Left Scratched	Repair
Seat Front Right Damaged	Repair
Seat Rear Dirty	Repair
Hood Lining Dirty	Repair
Door Sealing Rubber Front Right Damaged	Replace
Parcel Tray Damaged	Repair
Boot Carpet Damaged	Replace
Side Mirror Left Damaged	Replace
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Scratched	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Dented	Repair
Rear Fender Left Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Paintwork • Scratched	Repair
Rear bumper Damaged	Repair
Sill Panel Left Paintwork • Scratched	Repair
Sill Panel Right Damaged	Repair
Roof Dented	Repair
Control Arm(s) Front Axle Left Damaged	Replace
Tyre Front Left Worn	Replace
Tyre Front Right Worn	Replace
Rim Front Left Dented	Repair
Rim Rear Left Dented	Repair
Main Beam Right Dented	Repair
Chassis Dented	Repair
Belly plates Damaged	Replace
Radiator Cradle Damaged	Repair
Rear bumper stiffener cracked	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.5	2.42	-	
Rear	1.57	1.54	-	
Emergency / Parking	0.94	0.85	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALPM367854

DEKRA

CONDITION REPORT

Report No:
2017316250
DATE
23/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/70 R14	81T	Goodyear	Assurance	V	3322	0 mm
Front Right	165/70 R14	81T	Goodyear	Assurance	V	3922	0 mm
Rear Left	165/70 R14	81T	Goodyear	Assurance	V	3922	2 mm
Rear Right	165/70 R14	81T	Goodyear	Assurance	V	3922	3 mm
Spare	165/70 R14	81T	Goodyear	Assurance	V	3922	2 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ICU(INTEGRATED CENTRAL CONTROL UNIT)	B251E:00	LEFT STOP LAMP CIRCUIT SHORT TO GROUND	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Interior: Vehicle interior dirty and panels scratched.
Body • Exterior: Dents and scratches on body panels.Signs of impact damage to rear of vehicle.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALPM367854

DEKRA

CONDITION REPORT


Report No:
2017316250
DATE
23/10/2026



Brake and shock absorber repor



Diagnostic report page 1



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALPM367854

DEKRA

CONDITION REPORT

Report No:
2017316250
DATE
23/10/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALPM367854

DEKRA

CONDITION REPORT

Report No:
2017316250
DATE
23/10/2026



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel and Accessories

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALPM367854

DEKRA

CONDITION REPORT

Report No:
2017316250
DATE
23/10/2026



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis



Rear bumper stiffener

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALPM367854


DEKRA

CONDITION REPORT


Report No:
2017316250
DATE
23/10/2026




Oil cap and dipstick



Seat Front Right



Door Sealing Rubber Front Right



Seat Rear



Door Rear Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALPM367854

DEKRA

CONDITION REPORT

Report No:
2017316250
DATE
23/10/2026



Door Front Right



Bonnet



Bonnet



Front Fender Left



Front Fender Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALPM367854

DEKRA

CONDITION REPORT

Report No:
2017316250
DATE
23/10/2026



Door Front Left



Side Mirror Left



Door Rear Left



Rear Fender Left



Rear Fender Left



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALPM367854

DEKRA

CONDITION REPORT

Report No:
2017316250
DATE
23/10/2026


Rear bumper


Rear bumper


Front Fender Right


Water level


Sill Panel Right


Sill Panel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALPM367854

DEKRA

CONDITION REPORT

Report No:
2017316250
DATE
23/10/2026



Front Bumper


Front Bumper


Front Bumper


Belly plates


Tyre Front Right


Tyre Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALPM367854

DEKRA

CONDITION REPORT

Report No:
2017316250
DATE
23/10/2026



Rim Front Left



Radiator Cradle



Radiator Cradle



Engine



Chassis



Rim Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALPM367854

DEKRA

CONDITION REPORT

Report No:
2017316250
DATE
23/10/2026



Main Beam Right



Chassis



Control Arm(s) Front Axle Left



Water level



Roof



Parcel Tray

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALPM367854

DEKRA

CONDITION REPORT

Report No:
2017316250
DATE
23/10/2026



Boot Carpet



Headlight Left



Hood Lining

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALPM367854