DEKRA

CONDITION REPORT

Report No:
2017316040
DATE
22/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	22/10/2026		
Inspection Date	22/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	HYUNDAI	Registration Number	LT71SKGP
Model	GRAND I10	Register Number	
VIN	MALB251ALRM522570	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	115,919 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM522570

DEKRA

CONDITION REPORT

Report No:
2017316040
DATE
22/10/2026





Damage	Repair Way
Engine Oil Sweat	Repair
Engine Wiring Defective	Repair
Switch Electrical Window Winder rear right Damaged	Replace
Windscreen Wiper Damaged	Replace
Tail Light Left Defective	Repair
Tail Light Right Defective	Repair
Seat Front Left Dirty	Repair
Door Sealing Rubber Front Left Damaged	Replace
Parcel Tray Damaged	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Dented	Repair
Rear Fender Left Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Dented	Repair
Door Rear Left Dented	Repair
Door Rear Right Dented	Repair
Rear bumper Paintwork • Scratched	Repair
Inner Boot Floor Pan and Spare Wheel Well Dented	Repair
Sill Panel Left Damaged	Repair
Roof Dented	Repair
Parking Brake Performance Left / Right Difference out of legal range	Repair
Tyre Front Left Damaged	Replace
Tyre Rear Left Worn	Replace
Tyre Rear Right Damaged	Replace
Rim Front Right Dented	Repair
Rim Spare Wheel Dented	Repair
Chassis Dented	Repair
Belly plates Damaged	Replace
ABS warning light illuminated on	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.2	2.48	-	
Rear	1.59	1.62	-	
Emergency / Parking	1.16	0.11	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM522570

DEKRA

CONDITION REPORT

Report No:
2017316040
DATE
22/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/70 R14	81T	MRF	ZVTV	V	1322	4 mm
Front Right	165/70 R14	75H	Powertrac	Eco comfort	V	0126	4 mm
Rear Left	165/70 R14	81T	Goodyear	Assurance	V	5123	0 mm
Rear Right	165/70 R14	82H	Goodyear	Assurance	V	5123	1 mm
Spare	185/60 R14	75H	Powertrac	Radial	V	0120	4 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ABS/ESP(ANTI LOCK BRAKE/ELECTRONIC STABILITY PROGR	C1102:01	BATTERY VOLTAGE LOW	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: Interior: Sound amplifier fitted to vehicle.
Body • Exterior: Dents and scratches on body panels

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM522570

DEKRA

CONDITION REPORT

Report No:
2017316040
DATE
22/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE LEFT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM522570

DEKRA

CONDITION REPORT

Report No:
2017316040
DATE
22/10/2026



ODOMETER



DASHBOARD (W/ ENGINE RUNNING)



INTERIOR (FRONT DRIVER DOOR)



Manual Transmission



LF TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM522570


DEKRA

CONDITION REPORT

Report No:
2017316040
DATE
22/10/2026



RR TYRE TREAD



LR TYRE TREAD



Front chassis



Rear chassis



Oil cap and dipstick



Spare wheel and Accessories

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM522570

DEKRA

CONDITION REPORT

Report No:
2017316040
DATE
22/10/2026




ENGINE 1




VIN PLATE OR STICKER




LICENSE DISC



Brake and shock absorber repor



Diagnostic report page 1



Diagnostic report page 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM522570

DEKRA

CONDITION REPORT

Report No:
2017316040
DATE
22/10/2026




Switch Electrical Window Winder rear right



Door Front Right




Bonnet



Door Front Left



Door Front Left



Windscreen Wiper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM522570

DEKRA

CONDITION REPORT

Report No:
2017316040
DATE
22/10/2026



Door Rear Left



Rear Fender Left



Rear Fender Left



Seat Front Left



Door Sealing Rubber Front Left



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM522570

DEKRA

CONDITION REPORT

Report No:
2017316040
DATE
22/10/2026



Rear bumper




Rear bumper



Rim Spare Wheel



Parcel Tray



Tail Light Right



Tail Light Left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM522570

DEKRA

CONDITION REPORT

Report No:
2017316040
DATE
22/10/2026



Parking Brake Performance



Roof



Water level



Engine Wiring



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM522570

DEKRA

CONDITION REPORT

Report No:
2017316040
DATE
22/10/2026



Front Bumper



Sill Panel Left



Belly plates



Engine



Tyre Front Left



Chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM522570

DEKRA

CONDITION REPORT

Report No:
2017316040
DATE
22/10/2026



Tyre Rear Right



Tyre Rear Left



Inner Boot Floor Pan and Spare Wheel Well



Rim Front Right



Water level



Engine Wiring


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM522570

DEKRA

CONDITION REPORT

Report No:
2017316040
DATE
22/10/2026



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM522570