DEKRA

CONDITION REPORT

Report No:
2017309870
DATE
09/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	09/10/2026		
Inspection Date	09/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	HYUNDAI	Registration Number	MD05VMGP
Model	GRAND I10	Register Number	
VIN	MALB251ALSM539787	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/12/2026
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	87,913 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM539787

DEKRA

CONDITION REPORT

Report No:
2017309870
DATE
09/10/2026



Damage	Repair Way
Engine Oil Leak	Repair
Seat Rear Damaged	Repair
Door Sealing Rubber Front Right Damaged	Replace
Parcel Tray Damaged	Repair
Dash Padding Damaged	Repair
Front Bumper Residual Traces of Repair	Replace
Grill Damaged	Replace
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Defective	Repair
Rear Fender Left Dented	Repair
Front Fender Left / Inner Tray Damaged	Replace
Rear Fender Right / Inner Tray Damaged	Repair
Rear bumper Paintwork • Scratched	Repair
Rear Axle Damaged	Repair
Control Arm(s) Front Axle Left Damaged	Replace
Rim Front Left Dented	Repair
Chassis Dented	Repair
Belly plates Damaged	Replace
Fuel Tank Dented	Repair
Radiator Cradle Damaged	Repair
Loose sound wiring inside boot of vehicle	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s^2]
Front	2.55	2.56	-	
Rear	1.73	1.82	-	
Emergency / Parking	0.93	0.68	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/70 R14	81T	Anchee	AC808	V	2026	5 mm
Front Right	165/70 R14	81T	Anchee	AC808	V	2026	4 mm
Rear Left	165/70 R14	81T	Goodyear	Assurance	V	0924	1 mm
Rear Right	165/70 R14	81T	Goodyear	Assurance	V	0924	3 mm
Spare	165/70 R14	81T	Goodyear	Assurance	V	0924	5 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM539787

DEKRA

CONDITION REPORT

Report No:
2017309870
DATE
09/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	AB(AIRBAG)	B1102:00	BATTERY VOLTAGE LOW	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Interior: Vehicle interior dirty and panels scratched.
Body • Exterior: Poor residual traces of repair on body panels.Body panels misaligned.Stone chips and spray work on body panels.Dents and scratches on body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM539787


DEKRA

CONDITION REPORT


Report No:
2017309870
DATE
09/10/2026



Brake and shock absorber repor



Diagnostic report page 1



Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM539787

DEKRA

CONDITION REPORT

Report No:
2017309870
DATE
09/10/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM539787

DEKRA

CONDITION REPORT

Report No:
2017309870
DATE
09/10/2026



90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel and Accessories

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM539787

DEKRA

CONDITION REPORT

Report No:
2017309870
DATE
09/10/2026



LICENSE DISC



VIN PLATE OR STICKER


ENGINE 1


Front chassis


Rear chassis


Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM539787

DEKRA

CONDITION REPORT

Report No:
2017309870
DATE
09/10/2026



Loose sound wiring



Dash Padding



Door Sealing Rubber Front Right



Seat Rear



Seat Rear



Rear Fender Right / Inner Tray

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM539787


DEKRA

CONDITION REPORT

Report No:
2017309870
DATE
09/10/2026



Front Fender Right



Front Fender Left



Seat Rear



Rear bumper



Rear bumper



Parcel Tray

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM539787

DEKRA

CONDITION REPORT

Report No:
2017309870
DATE
09/10/2026



Rear bumper



Rear Fender Left



Bonnet



Bonnet



Water level



Engine

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM539787

DEKRA

CONDITION REPORT

Report No:
2017309870
DATE
09/10/2026



Front Bumper




Front Bumper



Front Bumper



Grill



Front Fender Left / Inner Tray



Rim Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM539787

DEKRA

CONDITION REPORT

Report No:
2017309870
DATE
09/10/2026



Radiator Cradle



Radiator Cradle



Belly plates



Radiator Cradle



Fuel Tank



Rear Axle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM539787

DEKRA

CONDITION REPORT

Report No:
2017309870
DATE
09/10/2026



Chassis



Control Arm(s) Front Axle Left



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM539787