DEKRA

CONDITION REPORT

Report No:
2017313000
DATE
16/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	16/10/2026		
Inspection Date	16/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	HYUNDAI	Registration Number	LT96TDGP
Model	GRAND I10	Register Number	
VIN	MALB251ALSM542781	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/06/2027
Color	SILVER	Power / Displacement	
Year Model		Paint Finish	M - METALLIC
Km Reading	133,908 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM542781

DEKRA

CONDITION REPORT

Report No:
2017313000
DATE
16/10/2026



Damage	Repair Way
Engine Oil Sweat	Repair
Switch Electrical Window Winder front right Defective	Repair
Tail Light Right Cracked	Replace
Front Bumper Damaged	Repair
Bonnet Dented	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Dented	Repair
Rocker Panel Right Dented	Repair
Roof Dented	Repair
Windscreen Chipped	Repair
Tyre Rear Right Damaged	Replace
Spare Tyre Torn / Cut	Replace
Chassis Damaged	Repair
Belly plates Damaged	Repair
Radiator Cradle Damaged	Replace
F/R electric window not working	Repair
Front tyre size differs	Replace

Brakes

Brake Test Results

Brake efficiency tested during road test.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.5	2.6	-	
Rear	1.7	1.7	-	
Emergency / Parking	1.1	1.2	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/70R14	81T	GoodYear	Assurance	V	0924	2 mm
Front Right	165/70R14	81T	Hankook	Kinergy	V	3314	1 mm
Rear Left	165/70R14	81T	GOODYEAR	Assurance	V	0924	2 mm
Rear Right	165/70R14	81S	Bridgestone	B250	V	2618	0 mm
Spare	165/80R14	85T	Apollo	Amazer	V	0000	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM542781

DEKRA

CONDITION REPORT

Report No:
2017313000
DATE
16/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	AIRBAG	B1102:00	BATTERY VOLTAGE LOW	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.SIGN OF SPRAY WORK DONE ON BODY PANELS

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM542781

DEKRA

CONDITION REPORT

Report No:
2017313000
DATE
16/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM542781

DEKRA

CONDITION REPORT

Report No:
2017313000
DATE
16/10/2026



INTERIOR (FRONT DRIVER DOOR)



Manual



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM542781

DEKRA

CONDITION REPORT

Report No:
2017313000
DATE
16/10/2026



ENGINE 1



ENGINE 2



Front chassis



Rear Chasis



Expansion Bottle



Water Level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM542781

DEKRA

CONDITION REPORT

Report No:
2017313000
DATE
16/10/2026



Oil and dipstick




LF TYRE TREAD



RF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



Sparewheel


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM542781

DEKRA

CONDITION REPORT


Report No:
2017313000
DATE
16/10/2026



Brake and Shocks Report



Diagnostic Report page 1



Diagnostic Report page 2



Radiator



Spare Tyre



Radiator Cradle


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM542781


DEKRA

CONDITION REPORT

Report No:
2017313000
DATE
16/10/2026



Belly plates



Radiator Cradle



Belly plates



Engine



Chassis



Chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM542781

DEKRA

CONDITION REPORT

Report No:
2017313000
DATE
16/10/2026



Tyre Rear Right



Front Bumper



Front Bumper



Windscreen



Tail Light Right



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM542781

DEKRA

CONDITION REPORT

Report No:
2017313000
DATE
16/10/2026



Roof



Rear bumper



Rear bumper



Bonnet



Bonnet



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM542781

DEKRA

CONDITION REPORT

Report No:
2017313000
DATE
16/10/2026



Switch Electrical Window Winder front right



Rocker Panel Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM542781