DEKRA

CONDITION REPORT

Report No:
2017316254
DATE
23/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	23/10/2026		
Inspection Date	23/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	HYUNDAI	Registration Number	MF12DKGP
Model	GRAND I10	Register Number	
VIN	MALB251ALSM619138	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/05/2027
Color	GREEN	Power / Displacement	
Year Model		Paint Finish	C - COMMON
Km Reading	99,837 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM619138

DEKRA

CONDITION REPORT

Report No:
2017316254
DATE
23/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Hoses Damaged	Repair
Electrical Window Winder front right Defective	Repair
Air Conditioner Defective	Repair
Interior Lights Defective	Repair
Headlight Left Damaged	Replace
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Damaged	Replace
Bonnet Dented	Repair
Front Fender Left Dented	Repair
Front Fender Right Dented	Repair
Rear Fender Left Dented	Repair
Front Fender Right / Inner Tray Damaged	Replace
Door Front Left Dented	Repair
Door Front Right Dented	Repair
Door Rear Left Dented	Repair
Door Rear Right Dented	Repair
Rear bumper Paintwork • Scratched	Repair
Sill Panel Left Dented	Repair
Windscreen Cracked	Replace
Tyre Front Left Smooth	Replace
Tyre Front Right Smooth	Replace
Spare Tyre Damaged	Replace
Rim Rear Left Dented	Repair
Main Beam Left Damaged	Repair
Belly plates Damaged	Replace
Radiator Cradle Damaged	
Radiator Cross Member Damaged	Repair
Jack Missing	Replace
Wheel Spanner Missing	Replace
Battery loose	Repair
Front Right Window defective	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.4	2.5	-	
Rear	1.5	1.3	-	
Emergency / Parking	1.1	1	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM619138

DEKRA

CONDITION REPORT

Report No:
2017316254
DATE
23/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/70R14	81T	Goodyear	Assurance	V	4724	1 mm
Front Right	165/70R14	81T	Goodyear	assurance	V	4524	1 mm
Rear Left	165/70R14	81T	Goodyear	Assurance	V	4724	2 mm
Rear Right	165/70R14	81T	Goodyear	Assurance	V	4724	3 mm
Spare	165/70R14	81T	Goodyear	assurance	V	0000	2 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	AB(AIRBAG)	B1102:00	BATTERY VOLTAGE LOW	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.SIGNS OF IMPACT DAMAGE FRONT OF VEHICLE / SIGNS OF SURFACE RUST FRONT LEFT MAIN BEAM.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Boitumelo Kutumela

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM619138

DEKRA

CONDITION REPORT

Report No:
2017316254
DATE
23/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM619138

DEKRA

CONDITION REPORT

Report No:
2017316254
DATE
23/10/2026



INTERIOR (FRONT DRIVER DOOR)



Manual



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM619138

DEKRA

CONDITION REPORT

Report No:
2017316254
DATE
23/10/2026



ENGINE 1



ENGINE 2




CHASSIS



Chasis



Oil cap and dipstick



LF TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM619138


DEKRA

CONDITION REPORT

Report No:
2017316254
DATE
23/10/2026



RF TYRE TREAD




LR TYRE TREAD




RR TYRE TREAD



Sparewheel



Brake report



Diagnostic Report page 1


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM619138

DEKRA

CONDITION REPORT

Report No:
2017316254
DATE
23/10/2026



Diagnostic Report page 2



Battery



Main beam left



Electrical Window Winder front right



Spare Tyre



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM619138


DEKRA

CONDITION REPORT

Report No:
2017316254
DATE
23/10/2026



Rear bumper



Rear bumper




Headlight Left



Water level



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM619138

DEKRA


CONDITION REPORT


Report No:
2017316254
DATE
23/10/2026





Front Bumper


Front Bumper


Front Fender Left


Front Fender Right


Door Front Right


Door Rear Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM619138

DEKRA

CONDITION REPORT

Report No: 2017316254
DATE 23/10/2026



Door Rear Left



Door Front Left




Rear Fender Left



Sill Panel Left



Tyre Front Left



Tyre Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM619138

DEKRA

CONDITION REPORT

Report No:
2017316254
DATE
23/10/2026



Belly plates



Front Fender Right / Inner Tray



Radiator Cross Member



Radiator Cross Member



Engine



Rim Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM619138

DEKRA

CONDITION REPORT

Report No:
2017316254
DATE
23/10/2026




Main Beam Left



Radiator Cradle



Side Mirror Right



Bonnet



Windscreen



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM619138

DEKRA

CONDITION REPORT

Report No:
2017316254
DATE
23/10/2026



Air Conditioner



Interior Lights

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM619138