DEKRA

# CONDITION REPORT

**Report No:**
**2017309113**
**DATE**
**08/10/2026**

*MFC Auction House*
*M57 Pretoria Rd, Glenmarais, KEMPTON PARK*
*Gauteng*

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572








## Assignment

| | | | |
|---|---|---|---|
| Client | MFC Auction House | Inspection Location | MFC<br>M57 Pretoria Road - 1619<br>Kempton Park - |
| Requested Date | 08/10/2026 | | |
| Inspection Date | 08/10/2026 | | |

## Vehicle Data

| | | | |
|---|---|---|---|
| Vehicle Type | PASSENGER VEHICLE | Registered Owner | MFC |
| Manufacturer | HYUNDAI | Registration Number | MR35PPGP |
| Model | GRAND I10 | Register Number | |
| VIN | MALB251ALSM685334 | Date Of First Licensing | |
| Engine Number | | Last COR | |
| Doors | 5 | License Expiry Date | |
| Color | WHITE | Power / Displacement | |
| Year Model | | Paint Finish | TWO COAT UNI |
| Km Reading | 30,641 KM | Fuel | PETROL |
| Cab / Body Type | HATCHBACK | Transmission | MANUAL |

## Vehicle Options & Accessories

**Items**

## VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM685334

DEKRA

# CONDITION REPORT

**Report No:**
**2017309113**
**DATE**
**08/10/2026**





| Damage | Repair Way |
|---|---|
| Rear Fender Left Paintwork • Scratched | Repair |
| Door Front Right Dented | Repair |
| Rear bumper Paintwork • Scratched | Repair |
| Roof Dented | Repair |
| Belly plates Damaged | Replace |
| Radiator Cradle Damaged | Repair |
| Deceleration service brake defective | Repair |

## Brakes

### Brake Test Results

| | Left | Right | | |
|---|---|---|---|---|
| | Braking Force [KN] | Braking Force [KN] | Axle Weight [KG] | Deceleration [m/s²] |
| **Front** | 2.48 | 2.52 | - | |
| **Rear** | 1.3 | 1.12 | - | |
| **Emergency / Parking** | 1.39 | 1.23 | - | |

## Tyres and Rims

### Tyre Specification & Measurement

| | Size | Load/Speed Index | Manufacture | Model | Type* | Production Date | Tread Depth (mm) |
|---|---|---|---|---|---|---|---|
| **Front Left** | 165/70 R14 | 81T | Goodyear | Assurance | V | 2825 | 2 mm |
| **Front Right** | 165/70 R14 | 81T | Goodyear | Assurance | V | 2725 | 2 mm |
| **Rear Left** | 165/70 R14 | 81T | Goodyear | Assurance | V | 2925 | 3 mm |
| **Rear Right** | 165/70 R14 | 81T | Goodyear | Assurance | V | 2825 | 3 mm |
| **Spare** | 165/70 R14 | 81T | Goodyear | Assurance | V | 2925 | 5 mm |

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM685334

DEKRA

# CONDITION REPORT

**Report No:**
**2017309113**
**DATE**
**08/10/2026**

## Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System | Code | Description | Status |
|---|---|---|---|---|
| 1 | ICU(INTEGRATED CENTRAL CONTROL UNIT) | B251E:00 | LEFT STOP LAMP CIRCUIT SHORT TO GROUND | |

## Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

## Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE EXTERIOR, INTERIOR, ELECTRICAL, AND MECHANICAL PARTS.Body • Exterior: Dents and scratches on body panels

## Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

## Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM685334

DEKRA

# CONDITION REPORT

**Report No:**
**2017309113**
**DATE**
**08/10/2026**




LICENSE DISC




VIN PLATE OR STICKER



FRONT RIGHT CORNER




90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM685334

DEKRA

# CONDITION REPORT

**Report No:**
**2017309113**
**DATE**
**08/10/2026**




90 DEGREE REAR



90 DEGREE RIGHT



INTERIOR (FRONT DRIVER DOOR)



Manual Transmission



DASHBOARD (W/ ENGINE RUNNING)




ODOMETER


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM685334

DEKRA

# CONDITION REPORT

**Report No:**
**2017309113**
**DATE**
**08/10/2026**



Brake and shock absorber repor




Front chassis



Rear chassis



LF TYRE TREAD



RR TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM685334

DEKRA

# CONDITION REPORT

**Report No:**
**2017309113**
**DATE**
**08/10/2026**



RF TYRE TREAD




ENGINE 1



Oil cap and dipstick



Diagnostic report page 1




Diagnostic report page 2



Spare wheel and Accessories

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM685334

DEKRA

# CONDITION REPORT


**Report No:**
**2017309113**
**DATE**
**08/10/2026**



Door Front Right



Rear bumper



Rear bumper



Rear bumper



Roof



Rear Fender Left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM685334

DEKRA

# CONDITION REPORT

**Report No:**
**2017309113**
**DATE**
**08/10/2026**



Rear Fender Left



Water level



Belly plates



Radiator Cradle



Radiator Cradle



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALSM685334