DEKRA

CONDITION REPORT

Report No:
2017305669
DATE
01/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	01/10/2026		
Inspection Date	01/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	HYUNDAI	Registration Number	KG30HKGP
Model	I20 1.0 TGDI FLUID 5-DR DCT [2021-2024]	Register Number	
VIN	MALBG511VNM091627	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/11/2026
Color	RED	Power / Displacement	
Year Model	2021	Paint Finish	M - METALLIC
Km Reading	131,774 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG511VNM091627

DEKRA

CONDITION REPORT

Report No:
2017305669
DATE
01/10/2026



Damage	Repair Way
Seat Front Left Torn / Cut	Repair
Seat Front Right Torn / Cut	Repair
Steering Wheel Trim Torn / Cut	Repair
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Damaged	Repair
Front Bumper Paintwork • Scratched	Repair
Door Front Left Dented	Repair
Door Front Right Dented	Repair
Door Rear Right Paintwork • Scratched	Repair
Fuel Flap Damaged	Repair
Windscreen Cracked	Replace
Tyre Rear Right Smooth	Replace
Spare Tyre Smooth	Replace
Rim Front Right Deformed	Repair
Belly plates Damaged	Repair
Steering Insufficient	Repair
Engine Noise Excessive	Repair
Warning lights illuminated	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.7	2.4	-	
Rear	2.0	2.3	-	
Emergency / Parking	1.2	1.5	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/55R16	91V	Anchee	AC808	V	0124	2 mm
Front Right	195/55R16	91V	Anchee	AC808	V	0124	1 mm
Rear Left	195/55R16	87V	Ceat	Securadrive	V	3121	2 mm
Rear Right	195/55R16	91V	Cachland	CH	V	2822	0 mm
Spare	195/55R16	87H	Bridgestone	Turanza	V	0000	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG511VNM091627

DEKRA

CONDITION REPORT

Report No:
2017305669
DATE
01/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	MOTOR DRIVEN POWER STEERING	C2413:01	MOTOR CURRENT FAIL(OVERCURRENT)	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.BODY EXTERIOR - SIGNS OF SPRAY WORK DONE ON BODY PANELS

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG511VNM091627

DEKRA

CONDITION REPORT

Report No:
2017305669
DATE
01/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG511VNM091627

DEKRA

CONDITION REPORT

Report No:
2017305669
DATE
01/10/2026



INTERIOR (FRONT DRIVER DOOR)



Automatic transmission



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG511VNM091627

DEKRA

CONDITION REPORT

Report No:
2017305669
DATE
01/10/2026



ENGINE 1



ENGINE 2



CHASSIS



REAR



Oil cap and dipstick



Expansion bottle


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG511VNM091627


DEKRA

CONDITION REPORT


Report No:
2017305669
DATE
01/10/2026



LF TYRE TREAD



RF TYRE TREAD




LR TYRE TREAD



RR TYRE TREAD



Sparewheel



Shock and brake

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG511VNM091627


DEKRA

CONDITION REPORT

Report No:
2017305669
DATE
01/10/2026




Diagnostic Report page 1



Diagnostic Report page 2



Warning lights illuminated



Side Mirror Right



Side Mirror Right



Seat Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG511VNM091627


DEKRA

CONDITION REPORT

Report No:
2017305669
DATE
01/10/2026



Seat Front Right




Side Mirror Right



Windscreen



Windscreen



Door Rear Right



Spare Tyre

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG511VNM091627

DEKRA

CONDITION REPORT

Report No:
2017305669
DATE
01/10/2026



Spare Tyre




Fuel Flap



Door Front Right



Door Front Left



Side Mirror Left



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG511VNM091627

DEKRA

CONDITION REPORT


Report No:
2017305669
DATE
01/10/2026




Door Front Right



Steering Wheel Trim



Front Bumper



Front Bumper



Tyre Rear Right



Belly plates

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG511VNM091627

DEKRA

CONDITION REPORT

Report No:
2017305669
DATE
01/10/2026



Belly plates



Rim Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG511VNM091627