DEKRA

CONDITION REPORT

Report No:
2017315130
DATE
21/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	21/10/2026		
Inspection Date	21/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	HYUNDAI	Registration Number	HK19TYGP
Model	CRETA	Register Number	
VIN	MALC381CLJM351896	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/11/2022
Color	GREY	Power / Displacement	
Year Model		Paint Finish	TWO COAT METALLIC
Km Reading	173,965 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALC381CLJM351896

DEKRA

CONDITION REPORT

Report No:
2017315130
DATE
21/10/2026



Damage	Repair Way
Dim Light Left Damaged	Replace
Bright Light Left Damaged	Replace
Seat Front Right Damaged	Repair
Door Panel Front Left Damaged	Repair
Door Panel Front Right Damaged	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Dented	Repair
Front Fender Left Damaged	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Paintwork • Scratched	Repair
Windscreen Chipped	Repair
Tyre Front Right Damaged	Replace
Tyre Rear Right Damaged	Replace
Spare Tyre Damaged	Replace
Rim Front Left Scratched	Repair
Brakes Noisy	Repair
Rear left and right tyre sizes different.	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.44	2.65	-	
Rear	2.54	2.19	-	
Emergency / Parking	1.71	1.28	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/65 R16	95H	Kumho	Solus	V	3716	1 mm
Front Right	205/65 R16C	107T	Pirelli	Carrier	V	1016	0 mm
Rear Left	205/65 R16	95H	Goodyear	Assurance	V	3120	1 mm
Rear Right	205/60 R16	92H	Bridgestone	Ecopia	V	1817	0 mm
Spare	215/65 R16	102V	Accelera	Radial	V	1213	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALC381CLJM351896

DEKRA

CONDITION REPORT

Report No:
2017315130
DATE
21/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENG(ENGINE)	P0562	SYSTEM VOLTAGE LOW	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Dents and scratches on body panels

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALC381CLJM351896

DEKRA

CONDITION REPORT

Report No:
2017315130
DATE
21/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALC381CLJM351896

DEKRA

CONDITION REPORT

Report No:
2017315130
DATE
21/10/2026



90 DEGREE RIGHT



Manual Transmission



ODOMETER



DASHBOARD (W/ ENGINE RUNNING)



Spare wheel and Accessories



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALC381CLJM351896


DEKRA

CONDITION REPORT

Report No:
2017315130
DATE
21/10/2026



ENGINE 1



Front chassis



Rear chassis



RR TYRE TREAD



LR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALC381CLJM351896


DEKRA

CONDITION REPORT


Report No:
2017315130
DATE
21/10/2026




LF TYRE TREAD



Brake and shock absorber repor



Diagnostic report page 1



Diagnostic report page 2



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALC381CLJM351896

DEKRA

CONDITION REPORT

Report No:
2017315130
DATE
21/10/2026



Door Panel Front Right



Seat Front Right



Water level



Rear Fender Right



Door Rear Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALC381CLJM351896

DEKRA

CONDITION REPORT

Report No:
2017315130
DATE
21/10/2026



Front Fender Right



Front Fender Right



Rear Fender Left



Door Rear Left



Front Fender Left



Rim Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALC381CLJM351896

DEKRA

CONDITION REPORT

Report No:
2017315130
DATE
21/10/2026



Bonnet



Windscreen



Bright Light Left



Dim Light Left



Spare Tyre



Tyre Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALC381CLJM351896

DEKRA

CONDITION REPORT

Report No:
2017315130
DATE
21/10/2026





Front Bumper


Front Bumper


Front Bumper


Tyre Front Right


Tyre Rear Right


Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALC381CLJM351896

DEKRA

CONDITION REPORT

Report No:
2017315130
DATE
21/10/2026



Door Front Right



Door Panel Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALC381CLJM351896