DEKRA

CONDITION REPORT

Report No:
2017314573
DATE
20/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	20/10/2026		
Inspection Date	20/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	HYUNDAI	Registration Number	HKJ473L
Model	VENUE 1.2 61KW MPI MOTION [2022-2024]	Register Number	
VIN	MALFB81BLPM405619	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/04/2027
Color	SILVER	Power / Displacement	
Year Model	2023	Paint Finish	TWO COAT UNI
Km Reading	98,795 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81BLPM405619

DEKRA

CONDITION REPORT

Report No:
2017314573
DATE
20/10/2026



Damage	Repair Way
Seat Rear Damaged	Repair
Hood Lining Dirty	Repair
Door Sealing Rubber Front Left Excessive Wear & Tear	Replace
Door Sealing Rubber Front Right Damaged	Replace
Boot Carpet Damaged	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Dented	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Damaged	Repair
Windscreen Cracked	Replace
Spare Tyre Damaged	Replace
Rim Spare Wheel Dented	Repair
Belly plates Damaged	Repair
Fuel Tank Sweat	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.38	2.03	-	
Rear	1.73	1.74	-	
Emergency / Parking	1.42	1.54	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/65 R15	91H	Bridgestone	Turanza	V	3217	1 mm
Front Right	195/65 R15	91H	Goodyear	Assurance	V	2322	1 mm
Rear Left	195/65 R15	91H	Goodyear	Assurance	V	2322	1 mm
Rear Right	195/65 R15	91H	Goodyear	Assurance	V	2322	4 mm
Spare	195/65 R15	91H	Goodyear	Assurance	V	0000	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81BLPM405619

DEKRA

CONDITION REPORT

Report No:
2017314573
DATE
20/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	AB(AIRBAG)	B1102:00	BATTERY VOLTAGE LOW	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81BLPM405619

DEKRA

CONDITION REPORT

Report No:
2017314573
DATE
20/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81BLPM405619

DEKRA

CONDITION REPORT

Report No:
2017314573
DATE
20/10/2026



INTERIOR (FRONT DRIVER DOOR)



Manual Transmission



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81BLPM405619

DEKRA

CONDITION REPORT

Report No:
2017314573
DATE
20/10/2026



ENGINE 1



Front chassis



Rear chassis



Oil cap and dipstick



LF TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81BLPM405619

DEKRA

CONDITION REPORT

Report No:
2017314573
DATE
20/10/2026




LR TYRE TREAD




RR TYRE TREAD




Spare wheel and Accessories



Brake and shock absorber repor



Diagnostic report page 1



Diagnostic report page 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81BLPM405619

DEKRA

CONDITION REPORT

Report No:
2017314573
DATE
20/10/2026



Door Rear Left



Door Front Right



Door Front Right



Door Sealing Rubber Front Right



Seat Rear



Seat Rear

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81BLPM405619


DEKRA

CONDITION REPORT

Report No:
2017314573
DATE
20/10/2026



Door Sealing Rubber Front Left



Hood Lining



Bonnet



Front Bumper



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81BLPM405619

DEKRA

CONDITION REPORT

Report No:
2017314573
DATE
20/10/2026



Windscreen



Water level



Water level



Spare Tyre



Rim Spare Wheel



Boot Carpet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81BLPM405619

DEKRA

CONDITION REPORT

Report No:
2017314573
DATE
20/10/2026



Front Bumper



Belly plates



Fuel Tank



Belly plates

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALFB81BLPM405619