DEKRA

CONDITION REPORT

Report No:
2017314067
DATE
19/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	19/10/2026		
Inspection Date	19/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	HYUNDAI	Registration Number	MN15XGGP
Model	GRAND CRETA 2.0 ELITE AT [2022-2026]	Register Number	
VIN	MALPC815MPM835280	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/08/2027
Color	BLUE	Power / Displacement	
Year Model	2023	Paint Finish	TWO COAT UNI
Km Reading	25,286 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALPC815MPM835280

DEKRA

CONDITION REPORT

Report No:
2017314067
DATE
19/10/2026





Damage	Repair Way
Center Console / Cubbyhole + Lid Defective	Repair
Switch Electrical Window Winder rear right Damaged	Replace
Tail Light Left Cracked	Replace
Headlight Right Damaged	Replace
Boot Carpet Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Residual Traces of Repair	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Residual Traces of Repair	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Residual Traces of Repair	Repair
Door Rear Left Damaged	Repair
Door Rear Right Residual Traces of Repair	Repair
Boot Lid / Hatch door Residual Traces of Repair	Repair
Rear bumper Damaged	Repair
Rocker Panel Left Paintwork • Scratched	Repair
Windscreen Chipped	Repair
Tyre Front Right Damaged	Replace
Tyre Rear Left Damaged	Replace
Rim Front Right Scratched	Repair
Chassis Damaged	Repair
Belly plates Damaged	Replace
Fuel Tank Dented	Repair
Radiator Cradle Damaged	Replace
Triangle Missing	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.62	2.78	-	
Rear	2.03	2.08	-	
Emergency / Parking	1.89	1.63	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	215/55 R18	95H	Apollo	Apterra	V	4522	3 mm
Front Right	215/55 R18	95H	Apollo	Apterra	V	4522	2 mm
Rear Left	235/55 R18	100H	Kumho	Solus	V	1819	4 mm
Rear Right	235/55 R18	100H	Kumho	Solus	V	1819	4 mm
Spare	215/60 R17	96H	Jk tyre	Royale		0000	7 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALPC815MPM835280

DEKRA

CONDITION REPORT

Report No:
2017314067
DATE
19/10/2026

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Rain at time of inspection
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.POOR RESIDUAL TRACES OF REPAIR ON BODY PANELS / SIGNS OF IMPACT DAMAGE TO FRONT OF VEHICLE / BODY PANELS MISALIGNED / STONE CHIPS AND SPRAY WORK ON BODY PANELS / BOTTOM OF ENGINE AND GEARBOX FULLY COVERED / SIGNS OF SURFACE RUST ON UNDERCARRIAGE.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALPC815MPM835280

DEKRA

CONDITION REPORT

Report No:
2017314067
DATE
19/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALPC815MPM835280


DEKRA

CONDITION REPORT

Report No:
2017314067
DATE
19/10/2026



INTERIOR (FRONT DRIVER DOOR)



Automatic Transmission



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALPC815MPM835280

DEKRA

CONDITION REPORT

Report No:
2017314067
DATE
19/10/2026



ENGINE 1




Front chassis



Rear chassis



Oil cap and dipstick



LR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALPC815MPM835280

DEKRA

CONDITION REPORT

Report No:
2017314067
DATE
19/10/2026




LF TYRE TREAD




RR TYRE TREAD




Spare wheel



Brake and shock absorber repor



Diagnostic report page 1



Diagnostic report page 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALPC815MPM835280


DEKRA

CONDITION REPORT

Report No:
2017314067
DATE
19/10/2026



Spare wheel Accessories




Rear Fender Right



Door Rear Right



Door Front Right



Front Fender Right



Tyre Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALPC815MPM835280

DEKRA

CONDITION REPORT

Report No:
2017314067
DATE
19/10/2026



Rim Front Right



Rear bumper



Rear bumper


Rear bumper



Boot Lid / Hatch door


Boot Carpet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALPC815MPM835280

DEKRA

CONDITION REPORT

Report No:
2017314067
DATE
19/10/2026



Tail Light Left




Center Console / Cubbyhole + Lid




Rear bumper



Rear Fender Left



Door Rear Left



Door Front Left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALPC815MPM835280

DEKRA

CONDITION REPORT

Report No:
2017314067
DATE
19/10/2026



Front Fender Left



Bonnet



Headlight Right



Tyre Rear Left



Rocker Panel Left



Front Bumper


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALPC815MPM835280

DEKRA

CONDITION REPORT

Report No:
2017314067
DATE
19/10/2026



Front Bumper



Front Bumper



Belly plates



Radiator Cradle



Chassis



Chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALPC815MPM835280

DEKRA

CONDITION REPORT

Report No:
2017314067
DATE
19/10/2026



Chassis



Fuel Tank



Windscreen



Water level



Water level



Switch Electrical Window Winder rear right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALPC815MPM835280