DEKRA

CONDITION REPORT

Report No:
2017315155
DATE
21/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	
Requested Date	21/10/2026		-
Inspection Date	21/10/2026		-

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	
Manufacturer	ASHOK LEYLAND	Registration Number	MH54NTGP
Model	DOST LS	Register Number	
VIN	MB1AA22E5PRCR1750	Date Of First Licensing	
Engine Number		Last COR	
Doors	2	License Expiry Date	30/04/2027
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	C - COMMON
Km Reading	2,154 KM	Fuel	PETROL
Cab / Body Type	SINGLE CAB	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MB1AA22E5PRCR1750

DEKRA

CONDITION REPORT

Report No:
2017315155
DATE
21/10/2026





Damage	Repair Way
Hoses Damaged	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.2	2.7	-	
Rear	1.5	1.7	-	
Emergency / Parking	1.4	1.5	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185R14C	8PR 102/100Q	CEAT	MILAZE	V	4523	5 mm
Front Right	185R14C	8PR 102/100Q	CEAT	MILAZE	V	4423	5 mm
Rear Left	185R14C	8PP 102/100Q	CEAT	MILAZE	V	4523	5 mm
Rear Right	185R14C	C8PR 102/100	CEAT	MILAZE	V	4423	5 mm
Spare	185R14LT	107/105R10	MRF	STEEL MASTER	V	0000	6 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MB1AA22E5PRCR1750

DEKRA

CONDITION REPORT

Report No:
2017315155
DATE
21/10/2026

Diagnostic

A vehicle diagnostic has not been conducted.

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MB1AA22E5PRCR1750

DEKRA

CONDITION REPORT

Report No:
2017315155
DATE
21/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MB1AA22E5PRCR1750

DEKRA

CONDITION REPORT

Report No:
2017315155
DATE
21/10/2026



INTERIOR (FRONT DRIVER DOOR)



Manual



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MB1AA22E5PRCR1750

DEKRA

CONDITION REPORT

Report No:
2017315155
DATE
21/10/2026



ENGINE 2



ENGINE 1



CHASSIS



Rear Chasis



Oil Cap and dipstick



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MB1AA22E5PRCR1750

DEKRA

CONDITION REPORT

Report No:
2017315155
DATE
21/10/2026



RF TYRE TREAD




LR TYRE TREAD



RR TYRE TREAD



Sparewheel



Brake Test



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MB1AA22E5PRCR1750

DEKRA

CONDITION REPORT

Report No:
2017315155
DATE
21/10/2026



Hoses

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MB1AA22E5PRCR1750