DEKRA

CONDITION REPORT

Report No:
2017316381
DATE
23/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	23/10/2026		
Inspection Date	23/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	SUZUKI	Registration Number	LF73VGGP
Model	SWIFT 1.2I GA 5-DR [2021-2025]	Register Number	
VIN	MBHCZC63S00C14115	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	WHITE	Power / Displacement	
Year Model	2023	Paint Finish	TWO COAT UNI
Km Reading	58,405 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00C14115

DEKRA

CONDITION REPORT

Report No:
2017316381
DATE
23/10/2026



Damage	Repair Way
Radio/CD/USB Damaged	Replace
Center Console / Cubbyhole + Lid Damaged	Replace
Tail Light Left Damaged	Replace
Headlight Left Damaged	Replace
Seat Front Right Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Doorstopper Front Right Damaged	Replace
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Roof Damaged	Repair
Windscreen Damaged	Replace
Tyre Rear Left Worn	Replace
Sub Frame Deformed	Repair
Radiator Cross Member Damaged	Replace
Airbag warning lights illuminated	repair
License disc missing	report

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.13	2.14	-	
Rear	1.3	1.2	-	
Emergency / Parking	0.59	0.67	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	175/65R14	82H	Annaite	Radial	V	3825	2 mm
Front Right	175/65R14	82H	Annaite	Radial	V	3825	2 mm
Rear Left	165/80R14	85T	Apollo	Radial	V	1023	0 mm
Rear Right	165/80R14	84T	Apollo	Radial	V	1023	1 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00C14115

DEKRA

CONDITION REPORT

Report No:
2017316381
DATE
23/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ABS/ESP	C1057	POWER SUPPLY VOLTAGE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. 21DTC'S AT TIME OF TESTING SEE DTC REPORT.Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels. Vehicle body in poor condition. Repair work done to vehicle below standard. Signs of impact damage to front of vehicle.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00C14115

DEKRA

CONDITION REPORT

Report No:
2017316381
DATE
23/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00C14115


DEKRA

CONDITION REPORT


Report No:
2017316381
DATE
23/10/2026




90 DEGREE RIGHT



Brake test.




Diagnostic.



Diagnostic.



Undercarriage front.



Undercarriage rear.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00C14115

DEKRA

CONDITION REPORT

Report No:
2017316381
DATE
23/10/2026



Oil cap and dipstick.




Manual.



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LF TYRE TREAD



LR TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00C14115


DEKRA

CONDITION REPORT

Report No:
2017316381
DATE
23/10/2026



RR TYRE TREAD



RF TYRE TREAD



VIN PLATE OR STICKER



ENGINE 1



Water level



Headlight Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00C14115


DEKRA

CONDITION REPORT

Report No:
2017316381
DATE
23/10/2026




Front Bumper




Front Bumper



Bonnet



Front Fender Left



Rear Fender Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00C14115

DEKRA

CONDITION REPORT

Report No:
2017316381
DATE
23/10/2026



Door Rear Left



Rear bumper




Rear bumper



Boot Lid / Hatch door



Door Rear Right



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00C14115


DEKRA

CONDITION REPORT

Report No:
2017316381
DATE
23/10/2026



Front Fender Right



Roof



Door Rear Right



Tail Light Left



Windscreen



Seat Front Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00C14115

DEKRA

CONDITION REPORT

Report No:
2017316381
DATE
23/10/2026




Doorstopper Front Right




Center Console / Cubbyhole + Lid




Radio/CD/USB



Tyre Rear Left



Radiator Cross Member



Sub Frame


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00C14115

DEKRA

CONDITION REPORT

Report No:
2017316381
DATE
23/10/2026



Sub Frame

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00C14115