DEKRA

CONDITION REPORT

Report No:
2017314847
DATE
20/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	20/10/2026		
Inspection Date	20/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	NISSAN	Registration Number	LDP584NW
Model	MAGNITE TURBO 1.0T ACENTA W/O LED 5-DR CVT [2022-2024]	Register Number	
		Date Of First Licensing	
VIN	MDHFBADD0Z0008331	Last COR	
Engine Number		License Expiry Date	30/11/2026
Doors	5	Power / Displacement	
Color	SILVER	Paint Finish	C - COMMON
Year Model	2022	Fuel	PETROL
Km Reading	58,377 KM	Transmission	AUTOMATIC
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0008331

DEKRA

CONDITION REPORT

Report No:
2017314847
DATE
20/10/2026



Damage	Repair Way
Center Console / Cubbyhole + Lid Defective	Repair
Front Bumper Paintwork • Scratched	Repair
Rear Fender Right Residual Traces of Repair	Repair
Door Front Right Residual Traces of Repair	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Residual Traces of Repair	Repair
Sealing / Rubber Front Door Right Defective	Repair
Sealing / Rubber Rear Door Left Defective	Replace
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Damaged	Repair
Reverse Camera damaged or Faulty	Repair
Rear Bumper some bolts missing	Repair
Warning light illuminated	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.5	2.6	-	
Rear	1.4	1.6	-	
Emergency / Parking	0.4	0.9	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/60R16	89H	Fronway	Ecogreen	V	4225	4 mm
Front Right	195/60R16	98H	Dronway	Ecogreen	V	4225	4 mm
Rear Left	195/60R16	89V	Apollo	alnac 4g	V	4623	4 mm
Rear Right	195/60R16	89V	apollo	Alnac	V	4623	4 mm
Spare	205/60R16	92H	Giti	GitiSynergy	V	0000	6 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0008331

DEKRA

CONDITION REPORT

Report No:
2017314847
DATE
20/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ABS	C1056:16	ECU SUPPLY VOLTAGE 1.DEF	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.POOR RESIDUAL TRACES OF REPAIR ON BODY PANELS / SOME BODY PARTS REQUIRE ALIGNMENT /

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0008331

DEKRA

CONDITION REPORT

Report No:
2017314847
DATE
20/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0008331

DEKRA

CONDITION REPORT

Report No:
2017314847
DATE
20/10/2026



INTERIOR (FRONT DRIVER DOOR)



Automatic



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0008331

DEKRA

CONDITION REPORT

Report No:
2017314847
DATE
20/10/2026



ENGINE 1




ENGINE 2




Chasis



CHASSIS



Oil cap and dipstick



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0008331

DEKRA

CONDITION REPORT

Report No:
2017314847
DATE
20/10/2026



RF TYRE TREAD




LR TYRE TREAD



RR TYRE TREAD



Spare wheel and Accessories



Brake report



Diagnostic Report page 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0008331

DEKRA

CONDITION REPORT


Report No:
2017314847
DATE
20/10/2026



Diagnostic Report page 2



Diagnostic Report page 3



Water level



Front Bumper



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0008331

DEKRA

CONDITION REPORT

Report No:
2017314847
DATE
20/10/2026



Door Front Right



Door Front Right



Door Rear Left



Door Rear Right



Door Rear Right



Door Rear Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0008331

DEKRA

CONDITION REPORT

Report No:
2017314847
DATE
20/10/2026



Rear Fender Right



Rear Fender Right




Boot Lid / Hatch door



Rear bumper



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0008331

DEKRA

CONDITION REPORT

Report No:
2017314847
DATE
20/10/2026



Sealing / Rubber Rear Door Left



Sealing / Rubber Front Door Right



Center Console / Cubbyhole + Lid

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0008331