DEKRA

CONDITION REPORT

Report No:
2017316038
DATE
22/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	22/10/2026		
Inspection Date	22/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	NISSAN	Registration Number	LGF070NW
Model	MAGNITE	Register Number	
VIN	MDHFBADD0Z0009549	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/05/2027
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	C - COMMON
Km Reading	54,035 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0009549

DEKRA

CONDITION REPORT

Report No:
2017316038
DATE
22/10/2026





Damage	Repair Way
Engine Oil Sweat	Repair
Door Sealing Rubber Front Right Worn	Repair
Front Bumper Paintwork • Scratched	Repair
Rear Fender Right Paintwork • Scratched	
Front Fender Right / Inner Tray Cracked	Repair
Door Rear Left Dented	Repair
Door Rear Right Dented	Repair
Boot Lid / Hatch door Residual Traces of Repair	Repair
Gearbox Oil Sweat	Repair
Body exterior	body has minor dents and scratches chip
Engine warning lights illumunated	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.6	2.7	-	
Rear	1.6	1.7	-	
Emergency / Parking	0.7	0.7	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/60R16	89V	DAVANTI	DX390	V	0624	4 mm
Front Right	195/60R16	89V	DAVANTI	DX390	V	0624	4 mm
Rear Left	195/60R16	89H	Wanderer	MRF	V	3722	4 mm
Rear Right	195/60R16	89H	Wanderer	Mrf	V	3722	4 mm
Spare	195/60R16	89H	Wanderer	mrf	V	///	5 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0009549

DEKRA

CONDITION REPORT

Report No:
2017316038
DATE
22/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE	P155D:00	GENERATOR	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Interior: Petrol flap lever/opener missing plastic display

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0009549

DEKRA

CONDITION REPORT

Report No:
2017316038
DATE
22/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0009549

DEKRA

CONDITION REPORT

Report No:
2017316038
DATE
22/10/2026



90 DEGREE RIGHT




DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic



Oil cap and dipstick



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0009549

DEKRA

CONDITION REPORT

Report No:
2017316038
DATE
22/10/2026




ENGINE 2




CHASSIS



Chasis



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0009549


DEKRA

CONDITION REPORT


Report No:
2017316038
DATE
22/10/2026



RF TYRE TREAD



Brake report



Diagnostics



Diagnostics



sparewheel



LICENSE DISC


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0009549

DEKRA

CONDITION REPORT

Report No:
2017316038
DATE
22/10/2026




VIN PLATE OR STICKER


Water level


Engine


Gearbox


Front Fender Right / Inner Tray


Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0009549

DEKRA

CONDITION REPORT

Report No:
2017316038
DATE
22/10/2026



Rear Fender Right




Boot Lid / Hatch door



Boot Lid / Hatch door



Door Rear Left



Front Bumper



Door Sealing Rubber Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0009549