DEKRA

CONDITION REPORT

Report No:
2017316365
DATE
28/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	28/10/2026		
Inspection Date	28/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	NISSAN	Registration Number	LW68ZJGP
Model	MICRA ACTIVE 1.2 VISIA 5-DR [2017-2018]	Register Number	
VIN	MDHFBUK13Z0302040	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/07/2025
Color	GREEN	Power / Displacement	
Year Model	2017	Paint Finish	TWO COAT METALLIC
Km Reading	1,234 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No:
2017316365
DATE
28/10/2026





Damage	Repair Way
Engine Wiring Damaged	Replace
Fuel Gauge Defective	Repair
Ref Counter Defective	Repair
Hooter Defective	Repair
Engine Management Lights Set	Repair
Windscreen Wiper Damaged	Repair
Headlight Left Damaged	Replace
Headlight Right Damaged	Replace
Dash Padding Damaged	Replace
Steering Wheel Trim Damaged	Replace
Side Mirror Right Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Bonnet slam plate (Shock tower/ Inner tray) Damaged	Repair
A • Pillar Right Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Roof Damaged	Repair
Windscreen Damaged	Replace
Gearbox Oil Leak	Repair
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
Radiator Cradle Damaged	Replace
Brakes Insufficient	Repair
Engine Noise Excessive	Repair
Rear tyres size differs	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	1.95	2.32	-	
Rear	1.8	1.79	-	
Emergency / Parking	1.35	1.33	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBUK13Z0302040

DEKRA

CONDITION REPORT

Report No:
2017316365
DATE
28/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/70R14	81T	Autogrip	Radial	V	0524	2 mm
Front Right	165/70R14	81T	Autogrip	Radial	V	0524	2 mm
Rear Left	175/65R14	82H	Autogrip	Radial	V	0124	3 mm
Rear Right	185/60R14	82H	Goodyear	Efficient	V	4123	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE	U1001	CAN COMMUNICATION CIRCUIT	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. 16 DTC'S AT TIME OF TESTING SEE DTC REPORT.Engine Compartment: Battery loose. Sump damaged.
Electrical Components and Instruments: radio antenna missing.
Interior: signs of vehicle airbags deployed. cluster does not work.
Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels. Repair work done to vehicle below standard. Vehicle body in poor condition. Signs of impact damage to front of vehicle.
Tyres and Rims: rear wheel sizes do not match.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBUK13Z0302040


DEKRA

CONDITION REPORT


Report No:
2017316365
DATE
28/10/2026



Brake test.



Diagnostic.



Diagnostic.



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBUK13Z0302040

DEKRA

CONDITION REPORT

Report No:
2017316365
DATE
28/10/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual.



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBUK13Z0302040

DEKRA

CONDITION REPORT


Report No:
2017316365
DATE
28/10/2026



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBUK13Z0302040

DEKRA

CONDITION REPORT

Report No:
2017316365
DATE
28/10/2026




VIN PLATE OR STICKER



ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBUK13Z0302040

DEKRA

CONDITION REPORT


Report No:
2017316365
DATE
28/10/2026


Engine Wiring


Headlight Left


Headlight Right


Front Bumper


Front Bumper


Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBUK13Z0302040


DEKRA

CONDITION REPORT

Report No:
2017316365
DATE
28/10/2026



Bonnet slam plate (Shock tower/ Inner tray)



Front Fender Left



Rear Fender Left



Door Front Left



Door Rear Left



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBUK13Z0302040

DEKRA

CONDITION REPORT


Report No:
2017316365
DATE
28/10/2026



Rear bumper



Rear bumper


Door Front Right


Door Rear Right


Front Fender Right


Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBUK13Z0302040

DEKRA

CONDITION REPORT

Report No:
2017316365
DATE
28/10/2026



A • Pillar Right



Roof



Windscreen



Windscreen Wiper



Side Mirror Right



Dash Padding

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBUK13Z0302040

DEKRA

CONDITION REPORT

Report No:
2017316365
DATE
28/10/2026



Steering Wheel Trim



Fuel Gauge



Ref Counter



Hooter



Engine Management Lights



CV Joint(s) Boot(s) Front Left (inner/outer)


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBUK13Z0302040

DEKRA

CONDITION REPORT

Report No:
2017316365
DATE
28/10/2026



Radiator Cradle



Radiator Cradle



Gearbox

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBUK13Z0302040