DEKRA

CONDITION REPORT

Report No:
2017309675
DATE
09/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	09/10/2026		
Inspection Date	09/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	RENAULT	Registration Number	BN99SKZN
Model	KWID	Register Number	
VIN	MEEBBA00400828769	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	SILVER	Power / Displacement	
Year Model		Paint Finish	M - METALLIC
Km Reading	78,659 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00400828769

DEKRA

CONDITION REPORT

Report No: 2017309675
DATE 09/10/2026



Damage	Repair Way
Engine Oil Leak	Repair
Clamps Damaged	Repair
Dim Light Left Defective	Repair
Seat Front Right Torn / Cut	Repair
Door Lock Boot Lid Damaged	Repair
Front Bumper Paintwork • Scratched	Repair
Front Fender Left Dented	Repair
Front Fender Right Dented	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Damaged	Repair
Windscreen Cracked	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Spare Tyre Smooth	Replace
Body exterior	Signs of spray work done on body panels
Body exterior	Minor dents scratches stone chips on body panels
Rear tyre size	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.0	2.3	-	
Rear	1.0	0.9	-	
Emergency / Parking	0.6	0.4	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/70R14	81H	Lanvigator	Comfort	V	4542	1 mm
Front Right	165/70R14	81H	Lanvigator	Comfort	V	4524	1 mm
Rear Left	165/70R13	79H	Sinful	SF	V	1119	4 mm
Rear Right	165/80R13	83T	Firesmax	FM601	V	0124	4 mm
Spare	165/70R14	81T	Ceat	Fuelsmart	V	0000	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00400828769

DEKRA

CONDITION REPORT

Report No:
2017309675
DATE
09/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	INJECTION	DTC025A13	FUEL PUMP RELAY CONTROL CIRCUIT OPEN CIRCUIT	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR, MINOR DENTS AND SCRATCHES NOTED ON VEHICLE BODY, EXTERIOR, INTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00400828769

DEKRA

CONDITION REPORT

Report No:
2017309675
DATE
09/10/2026




Shock and brake report



Diagnostics report



Diagnostics



Diagnostics report



Sparewheel



Coolant reservoir


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00400828769

DEKRA

CONDITION REPORT


Report No:
2017309675
DATE
09/10/2026



Dipstick



Manual transmission




Oil cap



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00400828769

DEKRA

CONDITION REPORT

Report No:
2017309675
DATE
09/10/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00400828769


DEKRA

CONDITION REPORT


Report No:
2017309675
DATE
09/10/2026



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00400828769

DEKRA

CONDITION REPORT

Report No:
2017309675
DATE
09/10/2026




REAR




ENGINE 1



ENGINE 2



CHASSIS



Front Fender Right



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00400828769

DEKRA

CONDITION REPORT

Report No:
2017309675
DATE
09/10/2026



Windscreen



Seat Front Right



Door Rear Right



Spare Tyre



Boot Lid / Hatch door



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00400828769


DEKRA

CONDITION REPORT

Report No:
2017309675
DATE
09/10/2026



Door Lock Boot Lid


Front Fender Left


Control Arm Bush(es) Front Axle Right


Front Bumper


Front Bumper


Control Arm Bush(es) Front Axle Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00400828769

DEKRA

CONDITION REPORT

Report No:
2017309675
DATE
09/10/2026



Engine



Clamps



Dim Light Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00400828769