DEKRA

CONDITION REPORT

Report No:
2017315589
DATE
21/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	22/10/2026		
Inspection Date	21/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	RENAULT	Registration Number	MH25WMGP
Model	KWID	Register Number	
VIN	MEEBBA00400832630	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/04/2027
Color	SILVER	Power / Displacement	
Year Model		Paint Finish	C - COMMON
Km Reading	102,466 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00400832630

DEKRA

CONDITION REPORT

Report No: 2017315589
DATE 21/10/2026



Damage	Repair Way
Engine Oil Leak	Repair
Headlight Right Damaged	Replace
Number Plate Front Missing	Replace
Number Plate Rear Missing	Replace
Front Bumper Damaged	Repair
Bonnet Dented	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Dented	Repair
Front Fender Left / Inner Tray Cracked	Replace
Door Front Left Paintwork • Scratched	Repair
Door Front Right Residual Traces of Repair	Repair
Door Rear Left Paintwork • Scratched	
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Dented	Repair
Inner Boot Floor Pan and Spare Wheel Well Damaged	Repair
Windscreen Chipped	Repair
Control Arm Bush(es) Front Axle Left Cracked	Replace
Gearbox Oil Sweat	Repair
Body exterior	residual traces of poor repair below standard

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	1.9	1.9	-	
Rear	1.2	1.2	-	
Emergency / Parking	0.6	0.7	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/70R14	81H	Hankook	Kinergy	V	1823	4 mm
Front Right	165/70R14	81T	CEAT	Fuelsmart	V	4922	4 mm
Rear Left	165/70R14	81T	Durun	hg918	V	3642	4 mm
Rear Right	165/70R14	81T	CEAT	fuelsmart	V	4922	4 mm
Spare	165/70R14	81T	CEAT	fuelsmart	V	4922	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00400832630

DEKRA

CONDITION REPORT

Report No:
2017315589
DATE
21/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	INJECTION	DTC033531	ENGINE SPEED SENSOR SIGNAL NO SIGNAL	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Front right inner fender missing.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00400832630

DEKRA

CONDITION REPORT

Report No:
2017315589
DATE
21/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00400832630

DEKRA

CONDITION REPORT

Report No:
2017315589
DATE
21/10/2026



90 DEGREE RIGHT



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Oil cap and Dipstick



ENGINE 1



ENGINE 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00400832630

DEKRA

CONDITION REPORT

Report No:
2017315589
DATE
21/10/2026




CHASSIS




Rear Chasis



RF TYRE TREAD



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00400832630


DEKRA

CONDITION REPORT


Report No:
2017315589
DATE
21/10/2026




sparewheel




manual




Brake report



diagnostics



diagnostics



diagnostics

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00400832630

DEKRA

CONDITION REPORT

Report No:
2017315589
DATE
21/10/2026



LICENSE DISC



VIN PLATE OR STICKER



Front Bumper



Front Bumper



Front Bumper



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00400832630

DEKRA

CONDITION REPORT

Report No:
2017315589
DATE
21/10/2026



Headlight Right



Door Front Right



Door Rear Right



Boot Lid / Hatch door



Number Plate Rear



Number Plate Front


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00400832630


DEKRA

CONDITION REPORT

Report No:
2017315589
DATE
21/10/2026



Rear Fender Left



Door Rear Left



Door Front Left



Windscreen



Windscreen



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00400832630

DEKRA

CONDITION REPORT

Report No:
2017315589
DATE
21/10/2026



Engine



Gearbox



Control Arm Bush(es) Front Axle Left



Inner Boot Floor Pan and Spare Wheel Well



Front Bumper



Front Fender Left / Inner Tray

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00400832630

DEKRA

CONDITION REPORT

Report No:
2017315589
DATE
21/10/2026



Headlight Right



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00400832630