# CONDITION REPORT

**Report No:**
**2017312585**
**DATE**
**15/10/2026**

*MFC Auction House*
*M57 Pretoria Rd, Glenmarais, KEMPTON PARK*
*Gauteng*

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572








## Assignment

| | | | |
|---|---|---|---|
| Client | MFC Auction House | Inspection Location | MFC<br>M57 Pretoria Road - 1619<br>Kempton Park - GT |
| Requested Date | 15/10/2026 | | |
| Inspection Date | 15/10/2026 | | |

## Vehicle Data

| | | | |
|---|---|---|---|
| Vehicle Type | PASSENGER VEHICLE | Registered Owner | |
| Manufacturer | RENAULT | Registration Number | KC98YMGP |
| Model | KWID | Register Number | |
| VIN | MEEBBA00500778545 | Date Of First Licensing | |
| Engine Number | | Last COR | |
| Doors | 5 | License Expiry Date | 31/12/2026 |
| Color | SILVER | Power / Displacement | |
| Year Model | | Paint Finish | M - METALLIC |
| Km Reading | 206,967 KM | Fuel | PETROL |
| Cab / Body Type | HATCHBACK | Transmission | MANUAL |

## Vehicle Options & Accessories

**Items**

## VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00500778545

DEKRA

# CONDITION REPORT

**Report No:**
**2017312585**
**DATE**
**15/10/2026**





| Damage | Repair Way |
|---|---|
| Engine Oil Leak | Repair |
| Air cleaner Torn / Cut | Repair |
| Headlight Left Damaged | Replace |
| Headlight Right Damaged | Replace |
| Door Handle Front Right Damaged | Replace |
| Rear Lower Valance Damaged | Repair |
| Front Bumper Damaged | Repair |
| Bonnet Damaged | Repair |
| Bonnet slam plate (Shock tower/ Inner tray) Damaged | Repair |
| Front Fender Left Damaged | Repair |
| Front Fender Right Dented | Repair |
| Front Fender Left / Inner Tray Damaged | Repair |
| Door Front Left Damaged | Repair |
| Door Rear Left Dented | Repair |
| Door Rear Right Dented | Repair |
| Boot Lid / Hatch door Residual Traces of Repair | Repair |
| Inner Boot Floor Pan and Spare Wheel Well Residual Traces of Repair | Repair |
| Control Arm Bush(es) Front Axle Left Cracked | Replace |
| Control Arm Bush(es) Front Axle Right Cracked | Replace |
| Tyre Front Left Excessive Wear & Tear | Replace |
| Tyre Front Right Excessive Wear & Tear | Replace |
| Tyre Rear Left Excessive Wear & Tear | Replace |
| Tyre Rear Right Excessive Wear & Tear | Replace |
| Spare Tyre Smooth | Replace |
| Main Beam Left Residual Traces of Repair | Repair |
| Main Beam Right Residual Traces of Repair | Repair |
| Rear tyre size differs | Replace |

## Brakes

### Brake Test Results

| | Left | Right | | |
|---|---|---|---|---|
| | Braking Force [KN] | Braking Force [KN] | Axle Weight [KG] | Deceleration [m/s²] |
| **Front** | 1.9 | 1.8 | - | |
| **Rear** | 1.1 | 1.1 | - | |
| **Emergency / Parking** | 1 | 1 | - | |

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00500778545

DEKRA

# CONDITION REPORT

**Report No:**
**2017312585**
**DATE**
**15/10/2026**

## Tyres and Rims

### Tyre Specification & Measurement

| | Size | Load/Speed Index | Manufacture | Model | Type* | Production Date | Tread Depth (mm) |
|---|---|---|---|---|---|---|---|
| **Front Left** | 185/65R14 | 86H | Goodyear | Efficient | V | 0922 | 0 mm |
| **Front Right** | 185/65R14 | 88H | Dunlop | Sport | V | 4017 | 0 mm |
| **Rear Left** | 185/60R15 | 82H | Atlas | Green | V | 3117 | 0 mm |
| **Rear Right** | 175/65R14 | 82H | Nexen | Nprize | V | 4224 | 0 mm |
| **Spare** | 165/70R14 | 81T | Ceat | Fuelsmart | V | 0000 | 0 mm |

* Tyre Legend: V=Virgin, R=Recap

## Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System | Code | Description | Status |
|---|---|---|---|---|
| 1 | INJECTION | DTC009517 | AIR TEMPERATURE SENSOR CIRCUIT SIGNAL OUTSIDE UPPE | |

## Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

## Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.SIGNS OF SPRAY WORK DONE ON BODY PANELS / RESIDUAL TRACES OF POOR REPAIR ON BODY PANELS

## Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

## Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00500778545

DEKRA

# CONDITION REPORT

**Report No:**
**2017312585**
**DATE**
**15/10/2026**



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00500778545

DEKRA

# CONDITION REPORT

**Report No:**
**2017312585**
**DATE**
**15/10/2026**



INTERIOR (FRONT DRIVER DOOR)



Manual transmission



DASHBOARD (W/ ENGINE RUNNING)




ODOMETER




LICENSE DISC




VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00500778545

DEKRA

# CONDITION REPORT

**Report No:**
**2017312585**
**DATE**
**15/10/2026**



ENGINE 1



ENGINE 2




CHASSIS



REAR



Coolant reservoir



Dipstick


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00500778545


DEKRA

# CONDITION REPORT


**Report No:**
**2017312585**
**DATE**
**15/10/2026**




ADDITIONAL 12



LF TYRE TREAD



RF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



Sparewheel


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00500778545


DEKRA

# CONDITION REPORT

**Report No:**
**2017312585**
**DATE**
**15/10/2026**




Shock and brake report




Diagnostic Report page 1



Diagnostic Report page 2



Diagnostic Report page 3



Diagnostic Report page 4



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00500778545

DEKRA

# CONDITION REPORT

**Report No:**
**2017312585**
**DATE**
**15/10/2026**



Door Handle Front Right



Door Rear Right



Spare Tyre



Inner Boot Floor Pan and Spare Wheel Well



Inner Boot Floor Pan and Spare Wheel Well



Inner Boot Floor Pan and Spare Wheel Well

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00500778545

DEKRA

# CONDITION REPORT

**Report No:**
**2017312585**
**DATE**
**15/10/2026**




Boot Lid / Hatch door



Boot Lid / Hatch door




Boot Lid / Hatch door



Door Rear Left



Door Front Left



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00500778545

DEKRA

# CONDITION REPORT

**Report No:**
**2017312585**
**DATE**
**15/10/2026**



Bonnet




Headlight Right



Headlight Right



Headlight Left



Bonnet slam plate (Shock tower/ Inner tray)



Tyre Front Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00500778545

DEKRA

# CONDITION REPORT

**Report No:**
**2017312585**
**DATE**
**15/10/2026**



Control Arm Bush(es) Front Axle Right




Front Bumper




Front Bumper



Tyre Front Left



Control Arm Bush(es) Front Axle Left



Front Fender Left / Inner Tray

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00500778545

DEKRA

# CONDITION REPORT

**Report No:**
**2017312585**
**DATE**
**15/10/2026**



Tyre Rear Left



Tyre Rear Right



Engine



Engine



Inner Boot Floor Pan and Spare Wheel Well



Inner Boot Floor Pan and Spare Wheel Well


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00500778545

DEKRA

# CONDITION REPORT

**Report No:**
**2017312585**
**DATE**
**15/10/2026**




Rear Lower Valance



Main Beam Right



Main Beam Right



Main Beam Right



Main Beam Left



Main Beam Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00500778545

DEKRA

# CONDITION REPORT

**Report No:**
**2017312585**
**DATE**
**15/10/2026**



Air cleaner



Air cleaner

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00500778545