DEKRA

CONDITION REPORT

Report No:
2017317275
DATE
26/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572








Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	26/10/2026		
Inspection Date	26/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	RENAULT	Registration Number	LCW020MP
Model	KIGER	Register Number	
VIN	MEEHBC00000113963	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/08/2027
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	C - COMMON
Km Reading	35,892 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00000113963

DEKRA

CONDITION REPORT

Report No:
2017317275
DATE
26/10/2026



Damage	Repair Way
Front Bumper Paintwork • Scratched	Repair
Bonnet Dented	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Right Paintwork • Chipmarks	Repair
Door Front Right Dented	Repair
Door Rear Right Dented	Repair
Sill Panel Left Paintwork • Scratched	Repair
Windscreen Cracked	Replace
Service Brake Performance Rear Axle Insufficient	Repair
Tyre Front Right Damaged	Replace
Gear Selections Slippy Hesitation	Repair
Warning light illuminated	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.1	2.2	-	
Rear	1.3	1.4	-	
Emergency / Parking	0.6	0.8	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/60R16	89H	MRF	WANDERER	V	1724	3 mm
Front Right	195/60R16	89H	MRF	Wanderer	V	1624	2 mm
Rear Left	195/60R16	89H	MRF	WANDERER	V	1624	4 mm
Rear Right	195/60R16	89H	WESTLAKE	ZUPERECO	V	5024	4 mm
Spare	165/80R14	85R	CEAT	TEMPORARY	V	0000	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00000113963

DEKRA

CONDITION REPORT

Report No:
2017317275
DATE
26/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	INJ(INJECTION)	DTC0226F1	BRAKE/ACCELERATION PEDAL POSITION SAFETY MODE 1 FLAG	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Boitumelo Kutumela

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00000113963


DEKRA

CONDITION REPORT


Report No:
2017317275
DATE
26/10/2026



BRAKE REPORT



Diagnostics




Diagnostics



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00000113963

DEKRA

CONDITION REPORT

Report No:
2017317275
DATE
26/10/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic



90 DEGREE FRONT



90 DEGREE LEFT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00000113963


DEKRA

CONDITION REPORT

Report No:
2017317275
DATE
26/10/2026




90 DEGREE RIGHT



LF TYRE TREAD



RR TYRE TREAD



LR TYRE TREAD



RF TYRE TREAD



Sparewheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00000113963


DEKRA

CONDITION REPORT

Report No:
2017317275
DATE
26/10/2026



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



Chasis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00000113963

DEKRA

CONDITION REPORT

Report No:
2017317275
DATE
26/10/2026



Oil Cap and dipstick



Sill Panel Left



Door Rear Right



Door Front Right



Front Bumper



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00000113963

DEKRA

CONDITION REPORT

Report No:
2017317275
DATE
26/10/2026



Rear Fender Right



Gear Selections




Bonnet



Bonnet



Windscreen



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00000113963

DEKRA

CONDITION REPORT

Report No:
2017317275
DATE
26/10/2026



Water level




Tyre Front Right



Tyre Front Right



Front Fender Right



Service Brake Performance Rear Axle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00000113963