DEKRA

CONDITION REPORT

Report No:
2017309873
DATE
09/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	09/10/2026		
Inspection Date	09/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	RENAULT	Registration Number	LW46CBGP
Model	TRIBER	Register Number	
VIN	MEERBC00200206262	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/06/2026
Color	SILVER	Power / Displacement	
Year Model		Paint Finish	TWO COAT METALLIC
Km Reading	76,725 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00200206262

DEKRA

CONDITION REPORT

Report No:
2017309873
DATE
09/10/2026



Damage	Repair Way
Headlight Left Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Door Front Left Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Window Rear Door Right Damaged	Replace
Sealing Window Rear Door Left Damaged	Repair
Control Arm(s) Front Axle Right Damaged	Replace
Tyre Front Left Worn	Replace
Rim Front Right Damaged	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	1.91	2.07	-	
Rear	1.45	1.38	-	
Emergency / Parking	0.76	0.8	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/80R14	85T	Ceat	Radial	V	1924	0 mm
Front Right	165/80R14	85T	Ceat	Radial	V	1924	1 mm
Rear Left	165/80R14	85T	Ceat	Radial	V	1924	2 mm
Rear Right	165/80R14	85T	Ceat	Radial	V	1924	2 mm
Spare	165/80R14	85R	Ceat	Radial	V	1724	2 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00200206262

DEKRA

CONDITION REPORT

Report No:
2017309873
DATE
09/10/2026

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels. Signs of impact damage to front of vehicle.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00200206262


DEKRA

CONDITION REPORT


Report No:
2017309873
DATE
09/10/2026



Brake test.



Diagnostic.



Diagnostic.



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00200206262

DEKRA

CONDITION REPORT

Report No:
2017309873
DATE
09/10/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual.



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00200206262

DEKRA

CONDITION REPORT


Report No:
2017309873
DATE
09/10/2026



90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00200206262

DEKRA

CONDITION REPORT

Report No:
2017309873
DATE
09/10/2026




VIN PLATE OR STICKER




ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



Oil cap and dipstick.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00200206262

DEKRA

CONDITION REPORT

Report No:
2017309873
DATE
09/10/2026



Water level



Headlight Left



Front Bumper



Bonnet



Front Bumper



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00200206262


DEKRA

CONDITION REPORT


Report No:
2017309873
DATE
09/10/2026



Door Front Left



Door Rear Left



Sealing Window Rear Door Left



Boot Lid / Hatch door



Door Rear Right



Window Rear Door Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00200206262

DEKRA

CONDITION REPORT

Report No:
2017309873
DATE
09/10/2026



Tyre Front Left



Control Arm(s) Front Axle Right



Rim Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00200206262