DEKRA

CONDITION REPORT

Report No:
2017306227
DATE
02/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	02/10/2026		
Inspection Date	02/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	RENAULT	Registration Number	LY31YJGP
Model	TRIBER	Register Number	
VIN	MEERBC00300208554	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/06/2027
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	C - COMMON
Km Reading	90,808 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00300208554

DEKRA

CONDITION REPORT

Report No:
2017306227
DATE
02/10/2026



Damage	Repair Way
Side Mirror Left Damaged	Repair
Side Mirror Right Damaged	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Residual Traces of Repair	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Dented	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Chipmarks	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Chipmarks	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Paintwork • Scratched	Repair
All four hup caps missing	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.2	2.6	-	
Rear	1.6	1.7	-	
Emergency / Parking	1.1	1.1	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/60R14	82H	Ling long	Crosswind	V	1523	4 mm
Front Right	185/60R14	82H	Maxxis	Radial	V	3509	3 mm
Rear Left	185/60R14	82H	Setula	Ever shine	V	3822	3 mm
Rear Right	185/60R14	82H	King Boss	G521	V	3222	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00300208554

DEKRA

CONDITION REPORT

Report No:
2017306227
DATE
02/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	MEMORY	DTC056016	COMPUTER SUPPLY VOLTAGE PERMANENT LOW LEVEL	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.BODY EXTERIOR - SIGNS OF SPRAY WORK DONE ON SOME BODY PANELS

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00300208554

DEKRA

CONDITION REPORT

Report No:
2017306227
DATE
02/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00300208554

DEKRA

CONDITION REPORT

Report No:
2017306227
DATE
02/10/2026



INTERIOR (FRONT DRIVER DOOR)



Manual



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00300208554

DEKRA

CONDITION REPORT

Report No:
2017306227
DATE
02/10/2026




ENGINE 1



ENGINE 2




CHASSIS



Expention bottle



Oil cap and dipstick



LF TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00300208554

DEKRA

CONDITION REPORT

Report No:
2017306227
DATE
02/10/2026



RF TYRE TREAD




LR TYRE TREAD




RR TYRE TREAD



Spare wheel



Shock and brake report



Diagnostic Report page 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00300208554

DEKRA

CONDITION REPORT

Report No:
2017306227
DATE
02/10/2026



Diagnostic Report page 2



Diagnostic Report page 3



Water level



Bonnet



Front Fender Left



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00300208554

DEKRA

CONDITION REPORT

Report No:
2017306227
DATE
02/10/2026



Door Rear Right



Door Front Right




Front Bumper



Front Bumper



Side Mirror Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00300208554

DEKRA

CONDITION REPORT

Report No:
2017306227
DATE
02/10/2026



Door Rear Left




Rear Fender Left




Boot Lid / Hatch door



Rear bumper



Rear bumper



Side Mirror Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00300208554