DEKRA

# CONDITION REPORT

**Report No:**
**2017311896**
**DATE**
**14/10/2026**

*MFC Auction House*
*M57 Pretoria Rd, Glenmarais, KEMPTON PARK*
*Gauteng*

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







## Assignment

| | | | |
|---|---|---|---|
| Client | MFC Auction House | Inspection Location | MFC<br>M57 Pretoria Road - 1619<br>Kempton Park - GT |
| Requested Date | 14/10/2026 | | |
| Inspection Date | 14/10/2026 | | |

## Vehicle Data

| | | | |
|---|---|---|---|
| Vehicle Type | PASSENGER VEHICLE | Registered Owner | |
| Manufacturer | HYUNDAI | Registration Number | MK62RLGP |
| Model | CRETA | Register Number | |
| VIN | MF3PB812LSJ146107 | Date Of First Licensing | |
| Engine Number | | Last COR | |
| Doors | 5 | License Expiry Date | 30/06/2027 |
| Color | GREY | Power / Displacement | |
| Year Model | | Paint Finish | M - METALLIC |
| Km Reading | 15,203 KM | Fuel | PETROL |
| Cab / Body Type | HATCHBACK | Transmission | MANUAL |

## Vehicle Options & Accessories

**Items**

## VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MF3PB812LSJ146107

DEKRA

# CONDITION REPORT

**Report No:**
**2017311896**
**DATE**
**14/10/2026**





| Damage | Repair Way |
|---|---|
| Front Bumper Paintwork • Scratched | Repair |
| Front Fender Left Paintwork • Scratched | Repair |
| Rear Fender Right Paintwork • Scratched | Repair |
| Door Front Left Dented | Repair |
| Door Front Right Paintwork • Scratched | Repair |
| Door Rear Left Paintwork • Scratched | Repair |
| Door Rear Right Paintwork • Scratched | Repair |
| Windscreen Cracked | Replace |

## Brakes

### Brake Test Results

| | Left | Right | | |
|---|---|---|---|---|
| | Braking Force [KN] | Braking Force [KN] | Axle Weight [KG] | Deceleration [m/s²] |
| **Front** | 3.1 | 2.9 | - | |
| **Rear** | 2.0 | 1.9 | - | |
| **Emergency / Parking** | 1.4 | 1.2 | - | |

## Tyres and Rims

### Tyre Specification & Measurement

| | Size | Load/Speed Index | Manufacture | Model | Type* | Production Date | Tread Depth (mm) |
|---|---|---|---|---|---|---|---|
| **Front Left** | 215/60R17 | 96H | Kumho | Solus | V | 2824 | 3 mm |
| **Front Right** | 215/60R17 | 96H | Kumho | Solus | V | 2824 | 3 mm |
| **Rear Left** | 215/60R17 | 96H | Kumho | Solus | V | 2824 | 3 mm |
| **Rear Right** | 215/60R17 | 96H | Kumho | Solus | V | 2924 | 3 mm |
| **Spare** | 215/60R17 | 96H | Kumho | Solus | V | 2924 | 4 mm |

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MF3PB812LSJ146107

DEKRA

# CONDITION REPORT

**Report No:**
**2017311896**
**DATE**
**14/10/2026**

## Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System | Code | Description | Status |
|---|---|---|---|---|
| 1 | AB (AIRBAG) (1 DTC) | B1116 | BATTERY VOLTAGE UNSTABLE | |

## Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

## Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

## Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

## Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MF3PB812LSJ146107

DEKRA

# CONDITION REPORT

**Report No:**
**2017311896**
**DATE**
**14/10/2026**



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MF3PB812LSJ146107


DEKRA

# CONDITION REPORT

**Report No:**
**2017311896**
**DATE**
**14/10/2026**



INTERIOR (FRONT DRIVER DOOR)



Manual



DASHBOARD (W/ ENGINE RUNNING)




ODOMETER




LICENSE DISC




VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MF3PB812LSJ146107

DEKRA

# CONDITION REPORT

**Report No:**
**2017311896**
**DATE**
**14/10/2026**



ENGINE 1



ENGINE 2




CHASSIS



Coolant bottle



Oil cap and dipstick



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MF3PB812LSJ146107

DEKRA

# CONDITION REPORT

**Report No:**
**2017311896**
**DATE**
**14/10/2026**



RF TYRE TREAD




LR TYRE TREAD




RR TYRE TREAD



Spare wheel



Shock and brake report



Diagnostic Report page 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MF3PB812LSJ146107

DEKRA

# CONDITION REPORT

**Report No:**
**2017311896**
**DATE**
**14/10/2026**




Diagnostic Report page 2




Water level




Windscreen



Door Rear Right



Door Front Right



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MF3PB812LSJ146107

DEKRA

# CONDITION REPORT


**Report No:**
**2017311896**
**DATE**
**14/10/2026**




Front Fender Left



Door Front Left



Door Rear Left



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MF3PB812LSJ146107