DEKRA

# CONDITION REPORT

**Report No:**
**2017309875**
**DATE**
**09/10/2026**

*MFC Auction House*
*M57 Pretoria Rd, Glenmarais, KEMPTON PARK*
*Gauteng*

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572








## Assignment

| | | | |
|---|---|---|---|
| Client | MFC Auction House | Inspection Location | MFC<br>M57 Pretoria Road - 1619<br>Kempton Park - |
| Requested Date | 09/10/2026 | | |
| Inspection Date | 09/10/2026 | | |

## Vehicle Data

| | | | |
|---|---|---|---|
| Vehicle Type | PASSENGER VEHICLE | Registered Owner | MFC |
| Manufacturer | TOYOTA | Registration Number | NF39YPGP |
| Model | AGYA 1.0 5-DR [2020-2023] | Register Number | |
| VIN | MHKA4DA5N0J005281 | Date Of First Licensing | |
| Engine Number | | Last COR | |
| Doors | 5 | License Expiry Date | |
| Color | SILVER | Power / Displacement | |
| Year Model | 2022 | Paint Finish | M - METALLIC |
| Km Reading | 107,680 KM | Fuel | PETROL |
| Cab / Body Type | HATCHBACK | Transmission | MANUAL |

## Vehicle Options & Accessories

**Items**

## VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MHKA4DA5N0J005281

DEKRA

# CONDITION REPORT

**Report No:**
**2017309875**
**DATE**
**09/10/2026**





| Damage | Repair Way |
|---|---|
| Front Bumper Residual Traces of Repair | Repair |
| Front Fender Right Residual Traces of Repair | Repair |
| Door Front Right Residual Traces of Repair | Repair |
| Door Rear Right Residual Traces of Repair | Repair |
| Tyre Rear Left Smooth | Replace |
| Rim Front Right Deformed | Repair |
| Body exterior | Signs of spray work done on body panels |
| Body exterior | Minor dents scratches stone chips on body panels |
| Body exterior | Residual traces of repair work done on body |
| Brake test failed | Repair |

## Brakes

### Brake Test Results

| | Left | Right | | |
|---|---|---|---|---|
| | Braking Force [KN] | Braking Force [KN] | Axle Weight [KG] | Deceleration [m/s²] |
| **Front** | 2.3 | 2.5 | - | |
| **Rear** | 1.6 | 1.6 | - | |
| **Emergency / Parking** | 0.5 | 0.5 | - | |

## Tyres and Rims

### Tyre Specification & Measurement

| | Size | Load/Speed Index | Manufacture | Model | Type* | Production Date | Tread Depth (mm) |
|---|---|---|---|---|---|---|---|
| **Front Left** | 165/45R16 | 74V | Aptany | Harmonic | V | 1625 | 2 mm |
| **Front Right** | 165/45R16 | 74V | Aptany | Harmonic | V | 1628 | 4 mm |
| **Rear Left** | 165/45R16 | 74V | Duraturn | Mozzo | V | 1623 | 0 mm |
| **Rear Right** | 165/45R16 | 74V | Duraturn | Mozzo | V | 1623 | 1 mm |
| **Spare** | 175/66R15 | 82T | Bridgestone | EP150 | V | 0000 | 5 mm |

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MHKA4DA5N0J005281

DEKRA

# CONDITION REPORT

**Report No:**
**2017309875**
**DATE**
**09/10/2026**

## Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System | Code | Description | Status |
|---|---|---|---|---|
| 1 | AIRBAG | B1806 | PASSENGER SEAT FRONTAL COLLISION SQUIB CIRCUIT OPEN CIRCUIT | |

## Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

## Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE EXTERIOR, INTERIOR, ELECTRICAL, AND MECHANICAL PARTS.

## Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

## Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MHKA4DA5N0J005281

DEKRA

# CONDITION REPORT

**Report No:**
**2017309875**
**DATE**
**09/10/2026**




LICENSE DISC



VIN PLATE OR STICKER



FRONT RIGHT CORNER




90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MHKA4DA5N0J005281

DEKRA

# CONDITION REPORT

**Report No:**
**2017309875**
**DATE**
**09/10/2026**




90 DEGREE REAR



90 DEGREE RIGHT



LR TYRE TREAD



LF TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MHKA4DA5N0J005281

DEKRA

# CONDITION REPORT

**Report No:**
**2017309875**
**DATE**
**09/10/2026**




INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)




ODOMETER



Manual transmission



REAR



ENGINE 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MHKA4DA5N0J005281

DEKRA

# CONDITION REPORT

**Report No:**
**2017309875**
**DATE**
**09/10/2026**



ENGINE 1



Coolant reservoir




Oil cap and dipstick



Sparewheel



CHASSIS



Shock and


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MHKA4DA5N0J005281


DEKRA

# CONDITION REPORT

**Report No:**
**2017309875**
**DATE**
**09/10/2026**




Diagnostics report


Front Fender Right


Door Front Right


Door Rear Right



Front Bumper


Rim Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MHKA4DA5N0J005281

DEKRA

# CONDITION REPORT

**Report No:**
**2017309875**
**DATE**
**09/10/2026**



Tyre Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MHKA4DA5N0J005281