DEKRA

CONDITION REPORT

Report No:
2017307881
DATE
07/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	07/10/2026		
Inspection Date	07/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	NISSAN	Registration Number	JY10NSGP
Model	JUKE 1.6 DDT TEKNA 5-DR [2011-2015]	Register Number	
VIN	SJNFAAF15U6114840	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/04/2027
Color	SILVER	Power / Displacement	
Year Model	2011	Paint Finish	M - METALLIC
Km Reading	232,383 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFAAF15U6114840

DEKRA

CONDITION REPORT

Report No:
2017307881
DATE
07/10/2026



Damage	Repair Way
Engine Oil Leak	Repair
Tail Light Left Cracked	Replace
Fog Light Front Right Cracked	Replace
Seat Front Right Torn / Cut	Replace
Door Sealing Rubber Rear Left Damaged	Replace
Parcel Tray Missing	Replace
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Right Paintwork • Flaking	Repair
Door Front Right Dented	Repair
Door Rear Right Residual Traces of Repair	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Paintwork • Scratched	Repair
Sealing Back Window Damaged	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Ball Joint(s) Front Axle Left Damaged	Replace
Ball Joint(s) Front Axle Right Loose / Excessive Play	Replace
Tyre Rear Left Smooth	Replace
Tyre Rear Right Smooth	Replace
Gearbox Oil Leak	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.4	3.0	-	
Rear	2.1	2.3	-	
Emergency / Parking	1.7	1	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	215/55R17	94V	Continental	Contact	V	3512	3 mm
Front Right	215/55R17	94V	Falken	Ziex	V	2218	3 mm
Rear Left	215/55R17	98V	Durun	M636	V	3019	0 mm
Rear Right	215/55R17	98V	Durun	M636	V	3019	0 mm
Spare	185/60R16	86M	Dunlop	Temporary	V	0000	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFAAF15U6114840

DEKRA

CONDITION REPORT

Report No:
2017307881
DATE
07/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ABS	C1109	BATTERY VOLTAGE (ABNORMAL)	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE EXTERIOR, INTERIOR, ELECTRICAL, AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFAAF15U6114840

DEKRA

CONDITION REPORT

Report No:
2017307881
DATE
07/10/2026



Shock and brake report



Diagnostics report



Diagnostics report



Sparewheel



Coolant reservoir



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFAAF15U6114840

DEKRA

CONDITION REPORT

Report No:
2017307881
DATE
07/10/2026



Manual transmission




FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFAAF15U6114840

DEKRA

CONDITION REPORT

Report No:
2017307881
DATE
07/10/2026



90 DEGREE FRONT




90 DEGREE RIGHT




90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFAAF15U6114840


DEKRA

CONDITION REPORT

Report No:
2017307881
DATE
07/10/2026



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



REAR



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFAAF15U6114840

DEKRA

CONDITION REPORT

Report No:
2017307881
DATE
07/10/2026




ENGINE 2



CHASSIS



Door Sealing Rubber Rear Left



Front Fender Right



Door Front Right



Seat Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFAAF15U6114840

DEKRA

CONDITION REPORT

Report No:
2017307881
DATE
07/10/2026



Door Rear Right



Rear Fender Right




Boot Lid / Hatch door



Parcel Tray



Tail Light Left



Sealing Back Window

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFAAF15U6114840

DEKRA

CONDITION REPORT

Report No:
2017307881
DATE
07/10/2026



Sealing Back Window



Control Arm Bush(es) Front Axle Right



Ball Joint(s) Front Axle Right



Fog Light Front Right



Control Arm Bush(es) Front Axle Left



Ball Joint(s) Front Axle Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFAAF15U6114840

DEKRA

CONDITION REPORT

Report No:
2017307881
DATE
07/10/2026



Tyre Rear Left



Tyre Rear Right



Rear bumper



Engine



Engine



Engine


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFAAF15U6114840

DEKRA

CONDITION REPORT

Report No:
2017307881
DATE
07/10/2026



Gearbox

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFAAF15U6114840