DEKRA

CONDITION REPORT

Report No:
2017318687
DATE
28/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	
Requested Date	29/10/2026		-
Inspection Date	28/10/2026		-

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	NISSAN	Registration Number	KWC608MP
Model	QASHQAI 1.5 DCI ACENTA DSL 5-DR [2014-2018]	Register Number	
		Date Of First Licensing	
VIN	SJNFAAJ11Z1780422	Last COR	
Engine Number		License Expiry Date	31/08/2025
Doors	5	Power / Displacement	
Color	WHITE	Paint Finish	TWO COAT UNI
Year Model	2016	Fuel	DIESEL
Km Reading	162,349 KM	Transmission	MANUAL
Cab / Body Type	SUV		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFAAJ11Z1780422

DEKRA

CONDITION REPORT

Report No:
2017318687
DATE
28/10/2026



Damage	Repair Way
Engine Oil Leak	Repair
Engine Management Lights Set	Repair
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Hood Lining Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Rear bumper Damaged	Repair
Windscreen Damaged	Replace
Tyre Front Left Worn	Replace
Tyre Front Right Worn	Replace
Tyre Rear Left Worn	Replace
Tyre Rear Right Worn	Replace
Rim Front Right Damaged	Replace
Warning light illuminated	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s^2]
Front	4.18	4.36	-	
Rear	2.69	3.08	-	
Emergency / Parking	0.88	1.18	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	215/60R17	96H	Dunlop	EC300	V	3318	0 mm
Front Right	215/60R17	96H	Dunlop	EC300	V	3318	0 mm
Rear Left	215/60R17	96H	Kumho	Radial	V	4622	0 mm
Rear Right	215/60R17	96T	Sailun	Radial	V	2324	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFAAJ11Z1780422

DEKRA

CONDITION REPORT

Report No:
2017318687
DATE
28/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	AIR BAG	B1422	SIDE COLLISION	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.SIGNS OF REPAIR WORK DONE TO BODY PANELS. POOR ALIGNMENT TO SOMEBODY PANELS. SIGNS OF AIRBAGS DEPLOYED ON LEFT SIDE OF VEHICLE.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFAAJ11Z1780422

DEKRA

CONDITION REPORT

Report No:
2017318687
DATE
28/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFAAJ11Z1780422

DEKRA

CONDITION REPORT

Report No:
2017318687
DATE
28/10/2026



INTERIOR (FRONT DRIVER DOOR)



Manual.



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFAAJ11Z1780422

DEKRA

CONDITION REPORT


Report No:
2017318687
DATE
28/10/2026



ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



Oil cap and dipstick.



LF TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFAAJ11Z1780422


DEKRA

CONDITION REPORT

Report No:
2017318687
DATE
28/10/2026




LR TYRE TREAD




RR TYRE TREAD




RF TYRE TREAD



Brake test.



Diagnostic Report page 1



Diagnostic Report page 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFAAJ11Z1780422


DEKRA

CONDITION REPORT

Report No:
2017318687
DATE
28/10/2026



Water level




Front Bumper



Front Bumper



Bonnet



Front Fender Left



Door Front Left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFAAJ11Z1780422

DEKRA

CONDITION REPORT

Report No:
2017318687
DATE
28/10/2026



Door Rear Left



Rear Fender Left



Rear bumper



Rear bumper



Door Front Right



Front Fender Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFAAJ11Z1780422

DEKRA

CONDITION REPORT

Report No:
2017318687
DATE
28/10/2026



Rear Fender Right




Seat Front Right




Windscreen



Engine Management Lights



Seat Front Left



Hood Lining

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFAAJ11Z1780422

DEKRA

CONDITION REPORT

Report No:
2017318687
DATE
28/10/2026



Tyre Rear Left



Tyre Rear Right



Tyre Front Left



Tyre Front Right



Engine



Rim Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFAAJ11Z1780422