DEKRA

CONDITION REPORT

Report No:
2017314858
DATE
21/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	21/10/2026		
Inspection Date	21/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	RENAULT	Registration Number	LDL926NW
Model	CAPTUR	Register Number	
VIN	VF12R051564196186	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/12/2026
Color	BEIGE	Power / Displacement	
Year Model		Paint Finish	C - COMMON
Km Reading	188,071 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF12R051564196186

DEKRA

CONDITION REPORT

Report No:
2017314858
DATE
21/10/2026



Damage	Repair Way
Caps Defective	Repair
Tail Light Right Damaged	Replace
Seat Front Right Torn / Cut	Repair
Front Bumper Damaged	Repair
Bonnet Dented	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Dented	Repair
Door Front Left Paintwork • Chipmarks	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Windscreen Cracked	Replace
Bolt(s) / Nut(s) Front Wheel Left Missing	Replace
Body exterior	Vehicle got some scratches, stone chips and dents
Boot not opening can not see spare wheel	Repair
Body exterior	Signs of spray work done on some body panels
Both front fender liner damage	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.0	3.3	-	
Rear	2.1	2.6	-	
Emergency / Parking	0.8	1.2	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/55R16	91V	Win run	R330	V	3925	3 mm
Front Right	205/55R16	91V	Powertrac	Eco comfort	V	1826	3 mm
Rear Left	205/55R16	91V	Win run	R330	V	3925	3 mm
Rear Right	205/55R16	91V	Win run	R330	V	3925	2 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF12R051564196186

DEKRA

CONDITION REPORT

Report No:
2017314858
DATE
21/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	MEMORY	DTC0300F8	MISFIRE POLLUTING MISFIRING	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF12R051564196186

DEKRA

CONDITION REPORT

Report No:
2017314858
DATE
21/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE LEFT



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF12R051564196186


DEKRA

CONDITION REPORT

Report No:
2017314858
DATE
21/10/2026



90 DEGREE REAR




Manual



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Oil cap and dipstick



Expention bottle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF12R051564196186


DEKRA

CONDITION REPORT

Report No:
2017314858
DATE
21/10/2026



ENGINE 1



RF TYRE TREAD



ENGINE 2



CHASSIS



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF12R051564196186

DEKRA

CONDITION REPORT


Report No:
2017314858
DATE
21/10/2026




RR TYRE TREAD




LICENSE DISC




VIN PLATE OR STICKER



Shock and brake report



Diagnostic report



Diagnostic report


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: VF12R051564196186


DEKRA

CONDITION REPORT


Report No:
2017314858
DATE
21/10/2026



Diagnostic report


Diagnostic report


Diagnostic report


Windscreen


Tail Light Right


Seat Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF12R051564196186

DEKRA

CONDITION REPORT

Report No:
2017314858
DATE
21/10/2026



Caps



Water level



Bonnet



Boot Lid / Hatch door



Rear Fender Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF12R051564196186

DEKRA

CONDITION REPORT

Report No:
2017314858
DATE
21/10/2026



Door Front Right



Front Bumper




Front Bumper



Front Bumper



Door Front Left



Door Rear Left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF12R051564196186

DEKRA

CONDITION REPORT

Report No:
2017314858
DATE
21/10/2026



Rear Fender Left



Rear bumper



Bolt(s) / Nut(s) Front Wheel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF12R051564196186