DEKRA

CONDITION REPORT

Report No:
2017314721
DATE
21/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	21/10/2026		
Inspection Date	21/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	TOYOTA	Registration Number	KR21LGGP
Model	YARIS 1.0 XS 5-DR [2015-2016]	Register Number	
VIN	VNKKL0D3X0A173675	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/12/2026
Color	BLUE	Power / Displacement	
Year Model	2015	Paint Finish	TWO COAT METALLIC
Km Reading	258,791 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VNKKL0D3X0A173675

DEKRA

CONDITION REPORT

Report No:
2017314721
DATE
21/10/2026





Damage	Repair Way
Bonnet stay and shocks Missing	Replace
Under bonnet insulation cover Damaged	Replace
Engine Management Lights Set	Repair
Switch Electrical Window Winder front right Damaged	Replace
Tail Light Right Damaged	Replace
Fog Light Front Left Damaged	Repair
Fog Light Front Right Damaged	Replace
Headlight Left Damaged	Replace
Headlight Right Damaged	Replace
Sun Visor Right Damaged	Replace
Side Mirror Right Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Roof Damaged	Replace
Windscreen Damaged	Replace
Tyre Rear Right Worn	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.38	2.49	-	
Rear	1.6	1.61	-	
Emergency / Parking	0.68	0.4	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65R15	88T	Continental	Contieco	V	4913	2 mm
Front Right	185/65R15	88H	Symmetry	Radial	V	2124	1 mm
Rear Left	185/60R15	88H	Dunlop	Sp	V	3522	2 mm
Rear Right	175/65R15	84H	Bridgestone	Radial	V	2517	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VNKKL0D3X0A173675

DEKRA

CONDITION REPORT

Report No:
2017314721
DATE
21/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE AND ECT	P0130	OXYGEN SENSOR CIRCUIT	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Electrical Components and Instruments: driver side electric window does not open.
Interior: gear lever damage.
Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels. Vehicle body in poor condition. Repair work done to vehicle below standerd. hatch door does not open.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE
19 DTC'S AT TIME OF TESTI
NG SEE DTC REPORT.

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VNKKL0D3X0A173675

DEKRA

CONDITION REPORT

Report No:
2017314721
DATE
21/10/2026



INTERIOR (FRONT DRIVER DOOR)



Manual.



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



FRONT RIGHT CORNER



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VNKKL0D3X0A173675

DEKRA

CONDITION REPORT

Report No:
2017314721
DATE
21/10/2026



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR



90 DEGREE RIGHT



ENGINE 1



Oil cap and dipstick.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VNKKL0D3X0A173675


DEKRA

CONDITION REPORT

Report No:
2017314721
DATE
21/10/2026




Undercarriage front.




Undercarriage rear.




LF TYRE TREAD



RF TYRE TREAD



RR TYRE TREAD



LR TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VNKKL0D3X0A173675


DEKRA

CONDITION REPORT


Report No:
2017314721
DATE
21/10/2026



Diagnostic.



Diagnostic.



Brake test.



LICENSE DISC



VIN PLATE OR STICKER



Water level


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VNKKL0D3X0A173675


DEKRA

CONDITION REPORT

Report No:
2017314721
DATE
21/10/2026



Headlight Left



Headlight Right




Fog Light Front Left



Fog Light Front Right



Tail Light Right



Bonnet stay and shocks


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VNKKL0D3X0A173675

DEKRA

CONDITION REPORT

Report No:
2017314721
DATE
21/10/2026



Under bonnet insulation cover



Front Bumper



Front Bumper



Bonnet



Front Fender Left



Rear Fender Left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VNKKL0D3X0A173675

DEKRA

CONDITION REPORT

Report No:
2017314721
DATE
21/10/2026



Door Front Left



Door Rear Left



Rear bumper



Rear bumper



Boot Lid / Hatch door



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VNKKL0D3X0A173675

DEKRA

CONDITION REPORT

Report No:
2017314721
DATE
21/10/2026



Front Fender Right



Door Front Right



Door Rear Right



Roof



Windscreen



Side Mirror Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VNKKL0D3X0A173675

DEKRA

CONDITION REPORT

Report No:
2017314721
DATE
21/10/2026



Engine Management Lights



Switch Electrical Window Winder front right



Sun Visor Right



Tyre Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VNKKL0D3X0A173675