DEKRA

CONDITION REPORT

Report No:
2017317774
DATE
27/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	27/10/2026		
Inspection Date	27/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	OPEL	Registration Number	JNF001NW
Model	CORSA	Register Number	
VIN	W0L0XEP68G4001298	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	GREY	Power / Displacement	
Year Model		Paint Finish	M - METALLIC
Km Reading	144,967 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: W0L0XEP68G4001298

DEKRA

CONDITION REPORT

Report No:
2017317774
DATE
27/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Expansion Bottle Water Leak	Replace
Windscreen Wiper Missing	Replace
Seat Front Right Damaged	Repair
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Paintwork • Flaking	Repair
Bonnet Dented	Repair
A • Pillar Left Defective	Repair
A • Pillar Right Defective	Repair
Front Fender Left Dented	Repair
Front Fender Right Dented	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Paintwork • Scratched	Repair
Roof Paintwork • Discoloured	Repair
Windscreen Cracked	Replace
Tie Rod End right Damaged	Replace
Tyre Rear Left Damaged	Replace
Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Right Missing	Replace
Engine Smoke Excessive	Repair
Body exterior	Vehicle got some scratches, stone chips and dents
Body exterior	Discoloring on some body panels
ABS and traction control light on	Repair
Computer box loose	Repair
Signs of water leak	Repair
R/R tire deferred size	Repair
VCI plug malfunction	Repair
Front suspension noisy	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.9	2.9	-	
Rear	1.7	1.9	-	
Emergency / Parking	1.6	1.9	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: W0L0XEP68G4001298

DEKRA

CONDITION REPORT

Report No:
2017317774
DATE
27/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65R15	88H	Goodyear	Efficient gr	V	4722	1 mm
Front Right	185/65R15	88H	Hilo	Genesys xp1	V	0921	2 mm
Rear Left	185/65R15	92H	Sumitomo	Htr h5	V	3822	0 mm
Rear Right	195/60R15	88V	Neolin	Neo green	V	0421	1 mm
Spare	195/65R15	91H	Road stone	Eurovis	V	0000	2 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

A vehicle diagnostic has not been conducted.
Diagnostic could not be performed due to no data available and or OBD interface malfunction.

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE: NORMAL WEAR AND TEAR MARKS ON THE BODY, INTERIOR, AND MECHANICAL.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: W0L0XEP68G4001298

DEKRA

CONDITION REPORT

Report No:
2017317774
DATE
27/10/2026



Shock and brake report



Spare wheel



Expention bottle



Oil cap and dipstick



Manual



Computer box loose

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: W0L0XEP68G4001298


DEKRA

CONDITION REPORT

Report No:
2017317774
DATE
27/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: W0L0XEP68G4001298

DEKRA

CONDITION REPORT


Report No:
2017317774
DATE
27/10/2026



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: W0L0XEP68G4001298

DEKRA

CONDITION REPORT

Report No:
2017317774
DATE
27/10/2026




RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: W0L0XEP68G4001298

DEKRA

CONDITION REPORT

Report No:
2017317774
DATE
27/10/2026



Seat Front Right



Engine Smoke




Bonnet



Front Bumper



Front Bumper



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: W0L0XEP68G4001298

DEKRA

CONDITION REPORT

Report No:
2017317774
DATE
27/10/2026



Side Mirror Left



Door Front Left



Door Rear Left



Rear Fender Left



Boot Lid / Hatch door



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: W0L0XEP68G4001298

DEKRA

CONDITION REPORT


Report No:
2017317774
DATE
27/10/2026



Rear bumper



Roof




Rear Fender Right



Door Rear Right



Door Front Right



Front Fender Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: W0L0XEP68G4001298

DEKRA

CONDITION REPORT


Report No:
2017317774
DATE
27/10/2026



Side Mirror Right



Water level




Windscreen



Windscreen Wiper



Engine



Tyre Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: W0L0XEP68G4001298

DEKRA

CONDITION REPORT

Report No:
2017317774
DATE
27/10/2026



Tie Rod End right



Bolt(s) / Nut(s) Rear Wheel Left



Bolt(s) / Nut(s) Rear Wheel Right



Expansion Bottle



A • Pillar Left



A • Pillar Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: W0L0XEP68G4001298