DEKRA

CONDITION REPORT

Report No:
2017312588
DATE
15/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	15/10/2026		
Inspection Date	15/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	MERCEDES-BENZ	Registration Number	KX03WBGP
Model	C200	Register Number	
VIN	W1K2060422R095756	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	30/06/2027
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	C - COMMON
Km Reading	147,114 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: W1K2060422R095756

DEKRA

CONDITION REPORT

Report No:
2017312588
DATE
15/10/2026





Damage	Repair Way
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Paintwork • Scratched	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Dented	Repair
Door Front Left Paintwork • Chipmarks	Repair
Door Front Right Dented	Repair
Door Rear Right Dented	Repair
Rear bumper Paintwork • Chipmarks	Repair
Engine light on	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.9	3.8	-	
Rear	3.0	3.0	-	
Emergency / Parking	2.1	2.4	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/45R18	95W	Anchee	Ac818	V	0526	3 mm
Front Right	225/45R18	95W	Anchee	Ac818	V	0526	3 mm
Rear Left	245/40R18	97W	Frun-two	Full run	V	0326	4 mm
Rear Right	245/40R18	97W	Frun-two	Full run	V	0326	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: W1K2060422R095756

DEKRA

CONDITION REPORT

Report No:
2017312588
DATE
15/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	STORED	B210D00	THE POWER SUPPLY IS TOO LOW	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: W1K2060422R095756

DEKRA

CONDITION REPORT

Report No:
2017312588
DATE
15/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: W1K2060422R095756

DEKRA

CONDITION REPORT

Report No:
2017312588
DATE
15/10/2026



INTERIOR (FRONT DRIVER DOOR)



Automatic




DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: W1K2060422R095756

DEKRA

CONDITION REPORT

Report No:
2017312588
DATE
15/10/2026



ENGINE 1



ENGINE 2




CHASSIS



Expention bottle



Oil cap



LF TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: W1K2060422R095756


DEKRA

CONDITION REPORT

Report No:
2017312588
DATE
15/10/2026



RF TYRE TREAD




LR TYRE TREAD



RR TYRE TREAD



No spare wheel



Shock and brake report



Diagnostic Report page 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: W1K2060422R095756

DEKRA


CONDITION REPORT


Report No:
2017312588
DATE
15/10/2026


Diagnostic Report page 2


Diagnostic Report page 3


Diagnostic Report page 4


Diagnostic Report page 5


Water level


Bonnet


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: W1K2060422R095756

DEKRA

CONDITION REPORT

Report No:
2017312588
DATE
15/10/2026



Rear Fender Right




Door Rear Right



Door Front Right



Front Bumper



Front Fender Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: W1K2060422R095756

DEKRA

CONDITION REPORT

Report No:
2017312588
DATE
15/10/2026



Rear Fender Left



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: W1K2060422R095756