DEKRA

CONDITION REPORT

Report No:
2017317280
DATE
28/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	28/10/2026		
Inspection Date	28/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	AUDI	Registration Number	N/A
Model	A3 SEDAN 1.8T FSI SE S TRONIC [2013-2017]	Register Number	
VIN	WAUZZZ8V4F1065967	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	31/03/2026
Color	WHITE	Power / Displacement	
Year Model	2015	Paint Finish	C - COMMON
Km Reading	218,290 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8V4F1065967

DEKRA

CONDITION REPORT

Report No:
2017317280
DATE
28/10/2026



Damage	Repair Way
Water level Insufficient	Repair
Tail Light Left Damaged	Replace
Seat Front Right Damaged	Repair
Side Mirror Left Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Paintwork • Scratched	Repair
Brake disc 1. Axle left Corrosion	Repair
Brake disc 1. Axle right Corrosion	Repair
Brake disc 2. Axle left Corrosion	Repair
Brake disc 2. Axle right Corrosion	Repair
Tyre Front Right Damaged	Replace
Engine Noise Excessive	Repair
Both number plates missing	Replace
Engine top cover missing	Replace
Engine light on	Repair
Signs of water leak can not pin point water leak	Repair
Hooter malfunction	Repair
Engine light illuminated	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.3	3.5	-	
Rear	2.7	3.4	-	
Emergency / Parking	1	1	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	255/45R17	94W	Powertrac	Racing pro	V	1624	3 mm
Front Right	225/45R17	94W	Rapid	Eco819	V	3922	0 mm
Rear Left	225/45R17	94W	Rapid	Eco819	V	3922	3 mm
Rear Right	225/45R17	94W	Rapid	Eco819	V	3922	3 mm
Spare	T125/70R18	99M	Continental	Temporary	V	////	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8V4F1065967

DEKRA

CONDITION REPORT

Report No:
2017317280
DATE
28/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ACTIVE STATIC	P105000	BANK 1, CAMSHAFT ADJUSTMENT VALVE EXHAUST OPEN CIR	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8V4F1065967


DEKRA

CONDITION REPORT

Report No:
2017317280
DATE
28/10/2026



Shock and brake report




Diagnostic report




Diagnostic report



Diagnostic report



Diagnostic report



Diagnostic report

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8V4F1065967

DEKRA

CONDITION REPORT

Report No:
2017317280
DATE
28/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER




DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8V4F1065967

DEKRA

CONDITION REPORT

Report No:
2017317280
DATE
28/10/2026



90 DEGREE RIGHT




90 DEGREE REAR




90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8V4F1065967

DEKRA

CONDITION REPORT

Report No:
2017317280
DATE
28/10/2026



RF TYRE TREAD



Spare wheel



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8V4F1065967

DEKRA

CONDITION REPORT

Report No:
2017317280
DATE
28/10/2026



CHASSIS



Expention bottle



Oil cap and dipstick



INTERIOR (FRONT DRIVER DOOR)



Water level



Seat Front Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8V4F1065967

DEKRA

CONDITION REPORT

Report No:
2017317280
DATE
28/10/2026



Rear Fender Right



Door Rear Right



Door Front Right



Front Fender Right



Front Bumper



Front Bumper


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8V4F1065967

DEKRA

CONDITION REPORT

Report No:
2017317280
DATE
28/10/2026




Front Fender Left




Side Mirror Left



Door Front Left



Door Rear Left



Rear Fender Left



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8V4F1065967

DEKRA

CONDITION REPORT

Report No:
2017317280
DATE
28/10/2026



Rear bumper



Boot Lid / Hatch door



Tail Light Left



Tyre Front Right



Brake disc 1. Axle right



Brake disc 1. Axle left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8V4F1065967

DEKRA

CONDITION REPORT

Report No:
2017317280
DATE
28/10/2026



Brake disc 2. Axle right



Brake disc 2. Axle left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8V4F1065967