DEKRA

CONDITION REPORT

Report No:
2017318082
DATE
27/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	27/10/2026		
Inspection Date	27/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	AUDI	Registration Number	LM38VMGP
Model	A4 35 TFSI 110KW S TRONIC [2020-2021]	Register Number	
VIN	WAUZZZF41MA023487	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	31/12/2026
Color	WHITE	Power / Displacement	
Year Model	2021	Paint Finish	TWO COAT UNI
Km Reading	202,811 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZF41MA023487

DEKRA

CONDITION REPORT

Report No:
2017318082
DATE
27/10/2026





Damage	Repair Way
Headlight Right Damaged	Replace
Seat Front Right Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Warning light illuminated	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	4.52	5.16	-	
Rear	2.77	3.52	-	
Emergency / Parking	1.39	2.38	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	245/40R18	97Y	Ceat	Radial	V	3224	2 mm
Front Right	245/40R18	97Y	Ceat	Radial	V	3223	2 mm
Rear Left	245/40R18	97Y	Bridgestone	Radial	V	4224	2 mm
Rear Right	245/40R18	97Y	Bridgestone	Radial	V	4224	2 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZF41MA023487

DEKRA

CONDITION REPORT

Report No:
2017318082
DATE
27/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE CONTROL MODULE 1	P253200	IGNITION SWITCH RUN POSITION CIRCUIT HIGH	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.SIGNS OF REPAIR WORK DONE TO BODY PANELS. POOR ALIGNMENT TO SOMEBODY PANELS. 100 DTC'S AT TIME OF TESTING SEE DTC REPORT.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZF41MA023487

DEKRA

CONDITION REPORT

Report No:
2017318082
DATE
27/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZF41MA023487

DEKRA

CONDITION REPORT

Report No:
2017318082
DATE
27/10/2026



INTERIOR (FRONT DRIVER DOOR)



Automatic.



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZF41MA023487

DEKRA

CONDITION REPORT

Report No:
2017318082
DATE
27/10/2026



ENGINE 1




Undercarriage front.




Undercarriage rear.



Oil cap.



LF TYRE TREAD



RR TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZF41MA023487

DEKRA

CONDITION REPORT


Report No:
2017318082
DATE
27/10/2026




LR TYRE TREAD




RF TYRE TREAD




Brake test.



Diagnostic Report page 1



Diagnostic Report page 2



Diagnostic Report page 3

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZF41MA023487

DEKRA

CONDITION REPORT


Report No:
2017318082
DATE
27/10/2026




Diagnostic Report page 4



Diagnostic Report page 5



Diagnostic Report page 6



Diagnostic Report page 7



Water level



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZF41MA023487

DEKRA

CONDITION REPORT


Report No:
2017318082
DATE
27/10/2026



Front Bumper




Bonnet



Front Fender Left



Door Rear Left



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZF41MA023487

DEKRA

CONDITION REPORT

Report No:
2017318082
DATE
27/10/2026



Boot Lid / Hatch door



Door Front Right



Seat Front Right



Headlight Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZF41MA023487