DEKRA

CONDITION REPORT

Report No:
2017314448
DATE
20/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	20/10/2026		
Inspection Date	20/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	BMW	Registration Number	KT93HNGP
Model	320I STEPTRONIC [2015-2019]	Register Number	
VIN	WBA8A16020NU76148	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	30/09/2027
Color	WHITE	Power / Displacement	
Year Model	2017	Paint Finish	C - COMMON
Km Reading	234,875 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA8A16020NU76148

DEKRA

CONDITION REPORT

Report No:
2017314448
DATE
20/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Side Mirror Right Damaged	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Dented	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Dented	Repair
Door Front Left Dented	Repair
Door Front Right Dented	Repair
Door Rear Left Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Cracked	Replace
Parking Brake Performance Left / Right Difference out of legal range	Repair
Bolt(s) / Nut(s) Front Wheel Left Missing	Repair
Bolt(s) / Nut(s) Front Wheel Right Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
Catalytic converter Damaged	Replace
Engine Smoke Excessive	Repair
Front tyres size differs	Replace
Rear tyres size differs	Replace
Warning light illuminated	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.3	3.1	-	
Rear	2.9	3.0	-	
Emergency / Parking	2.8	1.3	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/40R19	93Y	Goodyear	Eagle	V	3124	3 mm
Front Right	225/45R19	92W	Bridgestone	Potenza	V	4424	3 mm
Rear Left	235/35R19	91Y	Bridgestone	Potenza	V	1623	2 mm
Rear Right	255/35R19	92Y	Goodyear	Eagle	V	4821	2 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA8A16020NU76148

DEKRA

CONDITION REPORT

Report No:
2017314448
DATE
20/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	INTERMITTENT	930AA1	CRASH SAFETY MODULE UNDERVOLTAGE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA8A16020NU76148

DEKRA

CONDITION REPORT

Report No:
2017314448
DATE
20/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA8A16020NU76148

DEKRA

CONDITION REPORT

Report No:
2017314448
DATE
20/10/2026



INTERIOR (FRONT DRIVER DOOR)



Automatic




DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA8A16020NU76148

DEKRA

CONDITION REPORT

Report No:
2017314448
DATE
20/10/2026



ENGINE 1



ENGINE 2



CHASSIS



Oil cap



Expention bottle



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA8A16020NU76148

DEKRA

CONDITION REPORT

Report No:
2017314448
DATE
20/10/2026




RF TYRE TREAD




LR TYRE TREAD



RR TYRE TREAD



Shock and brake report



Diagnostic Report page 1



Diagnostic Report page 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA8A16020NU76148


DEKRA

CONDITION REPORT


Report No:
2017314448
DATE
20/10/2026


Diagnostic Report page 3


Diagnostic Report page 4


Diagnostic Report page 5


No spare wheel


Water level


Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA8A16020NU76148


DEKRA

CONDITION REPORT

Report No:
2017314448
DATE
20/10/2026



Bonnet



Parking Brake Performance



Rear Fender Right



Door Front Right



Front Fender Right



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA8A16020NU76148

DEKRA

CONDITION REPORT

Report No:
2017314448
DATE
20/10/2026



Front Bumper



Front Fender Left




Door Front Left



Door Rear Left



Rear Fender Left



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA8A16020NU76148

DEKRA

CONDITION REPORT

Report No:
2017314448
DATE
20/10/2026



Rear bumper




Side Mirror Right



Catalytic converter



Engine



Bolt(s) / Nut(s) Front Wheel Right



Bolt(s) / Nut(s) Front Wheel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA8A16020NU76148

DEKRA

CONDITION REPORT

Report No:
2017314448
DATE
20/10/2026



Bolt(s) / Nut(s) Rear Wheel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA8A16020NU76148