CONDITION REPORT

Report No:
2017317033
DATE
26/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	26/10/2026		
Inspection Date	26/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	MERCEDES-BENZ	Registration Number	FX64TXGP
Model	C200 BLUEEFFICIENCY [2011-2014]	Register Number	
VIN	WDD2040482R236226	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	31/01/2025
Color	WHITE	Power / Displacement	
Year Model	2012	Paint Finish	TWO COAT UNI
Km Reading	203,469 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040482R236226

DEKRA

CONDITION REPORT

Report No:
2017317033
DATE
26/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Hoses Defective	Replace
Air Conditioner Malfunction	Repair
Sun Visor Left Cracked	Repair
Brake Pedal Rubber Torn / Cut	Replace
Steering Wheel Trim Damaged	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
Rear Fender Right Paintwork • Scratched	Repair
Front Fender Right / Inner Tray Damaged	Repair
Door Front Right Dented	Repair
Door Rear Right Dented	Repair
Boot Lid / Hatch door Paintwork • Scratched	Replace
Rocker Panel Right Paintwork • Scratched	Repair
Windscreen Chipped	Repair
Stabilizer Mounting Front Right Damaged	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Spare Tyre Worn	Replace
Rim Front Left Scratched	Repair
Rim Rear Left Scratched	Repair
Rim Rear Right Scratched	Repair
Belly plates Damaged	Repair
Gearbox Oil Sweat	Repair
Engine Performance Idling / Hunting	Repair
Left and right interior B pillar covers damaged	Repair
Engine Management light illuminated on dashboard	Repair
Auxiliary battery inside boot missing	Replqxe
Foreign substance on oil cap	Repair
Rear prop shaft vibration rubber cracked	Replace
Signs of cylinder head casket blown	Replace
Spare wheel deflated	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.48	3.7	-	
Rear	2.85	3.05	-	
Emergency / Parking	2.15	2.49	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040482R236226

DEKRA

CONDITION REPORT

Report No:
2017317033
DATE
26/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/45 R17	94W	Symmetry	SY400	V	4123	4 mm
Front Right	225/45 R17	94W	Symmetry	SY400	V	3023	5 mm
Rear Left	225/45 R17	94W	A-Three	P606	V	4921	2 mm
Rear Right	225/45 R17	91W	Bridgestone	Potenza	V	1416	1 mm
Spare	225/45 R17	91W	Firestone	Touring	V	1319	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ECM(ENGINE CONTROL UNIT)	P001662	THE POSITION OF THE INTAKE CAMSHAFT(CYLINDER BANK1	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.ENGINE SPLASH PLATE MISSING

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040482R236226

DEKRA

CONDITION REPORT

Report No:
2017317033
DATE
26/10/2026


FRONT RIGHT CORNER


REAR LEFT CORNER


90 DEGREE FRONT


90 DEGREE REAR


90 DEGREE RIGHT


90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040482R236226

DEKRA

CONDITION REPORT

Report No:
2017317033
DATE
26/10/2026



INTERIOR (FRONT DRIVER DOOR)



Automatic Transmission



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040482R236226

DEKRA

CONDITION REPORT

Report No:
2017317033
DATE
26/10/2026



ENGINE 1



Front chassis



Rear chassis



Oil cap and dipstick



LF TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040482R236226


DEKRA

CONDITION REPORT

Report No:
2017317033
DATE
26/10/2026




LR TYRE TREAD




RR TYRE TREAD




Spare wheel and Accessories



Brake and shock absorber repor



Diagnostic report page 1



Diagnostic report page 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040482R236226


DEKRA

CONDITION REPORT

Report No:
2017317033
DATE
26/10/2026



Diagnostic report page 3




Diagnostic report page 4



Rear prop shaft vibration rubb



Left interior B pillar cover



Right interior B pillar cover



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040482R236226

DEKRA

CONDITION REPORT

Report No:
2017317033
DATE
26/10/2026



Boot Lid / Hatch door



Rim Rear Left



Sun Visor Left



Air Conditioner



Brake Pedal Rubber



Steering Wheel Trim


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040482R236226

DEKRA

CONDITION REPORT

Report No:
2017317033
DATE
26/10/2026



Rear Fender Right



Rear Fender Right



Door Rear Right



Door Front Right



Rim Rear Right



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040482R236226

DEKRA

CONDITION REPORT

Report No:
2017317033
DATE
26/10/2026



Bonnet



Rim Front Left



Spare Tyre



Windscreen



Front Fender Right / Inner Tray



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040482R236226

DEKRA

CONDITION REPORT

Report No:
2017317033
DATE
26/10/2026



Front Bumper



Front Bumper



Rocker Panel Right



Stabilizer Mounting Front Right



Engine



Gearbox

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040482R236226

DEKRA

CONDITION REPORT

Report No:
2017317033
DATE
26/10/2026



Control Arm Bush(es) Front Axle Left



Control Arm Bush(es) Front Axle Right



Belly plates



Belly plates



Water level



Hoses

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040482R236226