DEKRA

CONDITION REPORT

Report No:
2017316574
DATE
23/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	23/10/2026		
Inspection Date	23/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	MERCEDES-BENZ	Registration Number	JZT168MP
Model	C180 CGI BLUEEFFICIENCY AT [2010-2011]	Register Number	
VIN	WDD2040492R134608	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	31/05/2027
Color	WHITE	Power / Displacement	
Year Model	2010	Paint Finish	TWO COAT UNI
Km Reading	297,609 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040492R134608

DEKRA

CONDITION REPORT

Report No:
2017316574
DATE
23/10/2026



Damage	Repair Way
Engine Oil Leak	Repair
Central Air Vent Damaged	Replace
Engine Management Lights Set	Repair
Air Conditioner Insufficient	Repair
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Side Mirror Right Damaged	Replace
Front Bumper Damaged	Repair
Grill Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Windscreen Damaged	Replace
Tyre Rear Right Worn	Replace
Gearbox Oil Leak	Replace
Engine Noise Idling / Hunting	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.34	3.52	-	
Rear	2.09	2.39	-	
Emergency / Parking	1.94	2.39	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/55R16	91V	Anchee	Radial	V	0124	2 mm
Front Right	205/55R16	91V	Anchee	Radial	V	0824	2 mm
Rear Left	205/55R16	91V	Autogrip	Radial	V	0225	3 mm
Rear Right	205/55R16	91V	Lanvigator	Radial	V	1822	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040492R134608

DEKRA

CONDITION REPORT

Report No:
2017316574
DATE
23/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ECM	U010900	COMMUNICATION WITH FUEL PUMP HAS A MALFUNCTION	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. 73 DTC'S AT TIME OF TESTING SEE DTC REPORT.Electrical Components and Instruments: vehicle struggles to start. vehicle electronics malfunctioning.
Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040492R134608

DEKRA

CONDITION REPORT

Report No:
2017316574
DATE
23/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040492R134608


DEKRA

CONDITION REPORT


Report No:
2017316574
DATE
23/10/2026




90 DEGREE RIGHT




Brake test.




Diagnostic.



Diagnostic.



Diagnostic.



Diagnostic.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040492R134608


DEKRA

CONDITION REPORT

Report No:
2017316574
DATE
23/10/2026



Diagnostic.



Diagnostic.



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



Automatic.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040492R134608

DEKRA

CONDITION REPORT

Report No:
2017316574
DATE
23/10/2026




DASHBOARD (W/ ENGINE RUNNING)




ODOMETER



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040492R134608

DEKRA

CONDITION REPORT

Report No:
2017316574
DATE
23/10/2026



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Water level



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040492R134608

DEKRA

CONDITION REPORT

Report No:
2017316574
DATE
23/10/2026




Grill




Bonnet



Front Fender Left



Door Front Left



Door Rear Left



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040492R134608

DEKRA

CONDITION REPORT

Report No:
2017316574
DATE
23/10/2026




Rear bumper



Boot Lid / Hatch door



Rear Fender Right



Front Fender Right



Door Front Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040492R134608

DEKRA

CONDITION REPORT

Report No:
2017316574
DATE
23/10/2026



Windscreen



Seat Front Right



Seat Front Left



Engine Management Lights



Seat Front Right



Side Mirror Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040492R134608

DEKRA

CONDITION REPORT

Report No:
2017316574
DATE
23/10/2026




Tyre Rear Right



Engine



Gearbox



Central Air Vent



Air Conditioner

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040492R134608