DEKRA

CONDITION REPORT

Report No:
2017327009
DATE
18/11/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	18/11/2026		
Inspection Date	18/11/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	MERCEDES-BENZ	Registration Number	FK43BCGP
Model	C220	Register Number	
VIN	WDD2050042R038726	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	
Color	GREY	Power / Displacement	
Year Model		Paint Finish	M - METALLIC
Km Reading	285,954 KM	Fuel	DIESEL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050042R038726

DEKRA

CONDITION REPORT

Report No: 2017327009
DATE 18/11/2026



Damage	Repair Way
Engine Oil Leak	Repair
Front Bumper Paintwork • Chipmarks	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Paintwork • Chipmarks	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Dented	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Dented	Repair
Door Rear Right Dented	Repair
Rear bumper Paintwork • Scratched	Repair
Roof Residual Traces of Repair	Repair
Body exterior	Vehicle got minor scratches, stone chips and dents
No license disc	Replace
Boot not opening	Repair
Body exterior	Signs of spray work done on some body panels

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.5	3.8	-	
Rear	2.7	2.8	-	
Emergency / Parking	1.8	1.9	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/50R17	94W	Bridgestone	Potenza	V	0625	1 mm
Front Right	225/50R17	94V	Dunlop	Sp sport	V	0207	3 mm
Rear Left	215/50R17	95Y	Continental	Contact	V	3720	2 mm
Rear Right	225/50R17	94W	Bridgestone	Potenza	V	4917	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050042R038726

DEKRA

CONDITION REPORT

Report No:
2017327009
DATE
18/11/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ACTIVE AND STORED	B1F4500	THE STARTER BATTERY HAS EXCESSIVE RESISTANCE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE: NORMAL WEAR AND TEAR MARKS ON THE BODY, INTERIOR, AND MECHANICAL.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050042R038726

DEKRA

CONDITION REPORT

Report No:
2017327009
DATE
18/11/2026




Shock and brake report




Diagnostic report



Diagnostic report



Diagnostic report



Diagnostic report



Automatic

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050042R038726

DEKRA

CONDITION REPORT

Report No:
2017327009
DATE
18/11/2026




Expention bottle



Oil cap and dipstick



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050042R038726

DEKRA

CONDITION REPORT

Report No:
2017327009
DATE
18/11/2026



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050042R038726

DEKRA

CONDITION REPORT


Report No:
2017327009
DATE
18/11/2026



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050042R038726

DEKRA

CONDITION REPORT

Report No:
2017327009
DATE
18/11/2026



ENGINE 2




CHASSIS



Water level



Bonnet



Rear Fender Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050042R038726

DEKRA

CONDITION REPORT

Report No:
2017327009
DATE
18/11/2026



Door Front Right



Front Fender Right



Front Bumper



Front Bumper



Front Fender Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050042R038726


DEKRA

CONDITION REPORT

Report No:
2017327009
DATE
18/11/2026



Door Rear Left



Rear Fender Left



Rear bumper



Rear bumper



Rear bumper



Engine

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050042R038726

DEKRA

CONDITION REPORT

Report No:
2017327009
DATE
18/11/2026



Roof

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050042R038726