DEKRA

CONDITION REPORT

Report No:
2017305421
DATE
30/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	30/09/2026		
Inspection Date	30/09/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	FORD	Registration Number	LL49CLGP
Model	KUGA 2.0 ECOBOOST ST LINE AWD AT [2018-2021]	Register Number	
		Date Of First Licensing	
VIN	WF0AXXWPMAJA25127	Last COR	
Engine Number		License Expiry Date	31/10/2026
Doors	5	Power / Displacement	
Color	WHITE	Paint Finish	M - METALLIC
Year Model	2019	Fuel	PETROL
Km Reading	128,535 KM	Transmission	AUTOMATIC
Cab / Body Type	STATION WAGON		

Vehicle Options & Accessories

Items


VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No:
2017305421
DATE
30/09/2026





Damage	Repair Way
Front Bumper Paintwork • Chipmarks	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Paintwork • Chipmarks	Repair
Front Fender Right Paintwork • Chipmarks	Repair
Door Front Right Paintwork • Chipmarks	Repair
Door Rear Left Paintwork • Chipmarks	Repair
Door Rear Right Paintwork • Chipmarks	Repair
Windscreen Cracked	Replace
Engine light on	Repair
Brakes	No brake test done vehicle is 4wd

Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	245/45R17	102W	Royal black	Royal explor	V	3124	1 mm
Front Right	245/45R17	102W	Royal black	Royal explor	V	3124	1 mm
Rear Left	245/45R17	102W	Royal black	Royal explor	V	4024	2 mm
Rear Right	245/45R17	102W	Royal black	Royal explor	V	3124	2 mm
Spare	T155/70R17	110M	Maxxis	Temporary	V	3118	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WF0AXXWPMAJA25127

DEKRA

CONDITION REPORT

Report No:
2017305421
DATE
30/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	CMDTCS	U2013:87-28	SWITCH PACK	

Inspection Conditions

No Test Drive
Rain at time of inspection
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WF0AXXWPMAJA25127


DEKRA

CONDITION REPORT


Report No:
2017305421
DATE
30/09/2026



Shock report



Diagnostic report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WF0AXXWPMAJA25127

DEKRA

CONDITION REPORT

Report No:
2017305421
DATE
30/09/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WF0AXXWPMAJA25127

DEKRA

CONDITION REPORT


Report No:
2017305421
DATE
30/09/2026



90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WF0AXXWPMAJA25127

DEKRA

CONDITION REPORT

Report No:
2017305421
DATE
30/09/2026



LICENSE DISC



VIN PLATE OR STICKER




ENGINE 1



ENGINE 2



CHASSIS



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WF0AXXWPMAJA25127

DEKRA

CONDITION REPORT

Report No:
2017305421
DATE
30/09/2026



Expention bottle



Windscreen



Water level



Windscreen



Bonnet



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WF0AXXWPMAJA25127


DEKRA

CONDITION REPORT

Report No:
2017305421
DATE
30/09/2026



Door Front Right



Front Fender Right



Front Bumper



Front Bumper



Front Fender Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WF0AXXWPMAJA25127