DEKRA

CONDITION REPORT

Report No:
2017324195
DATE
11/11/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	11/11/2026		
Inspection Date	11/11/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	MINI	Registration Number	JT95KXGP
Model	COOPER S CLUBMAN 2.0 5-DR STEPTRONIC [2019-2024]	Register Number	
		Date Of First Licensing	
VIN	WMWLV720502N88967	Last COR	
Engine Number		License Expiry Date	31/03/2027
Doors	5	Power / Displacement	
Color	SILVER	Paint Finish	M - METALLIC
Year Model	2020	Fuel	PETROL
Km Reading	191,430 KM	Transmission	AUTOMATIC
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WMWLV720502N88967

DEKRA

CONDITION REPORT

Report No:
2017324195
DATE
11/11/2026



Damage	Repair Way
Seat Front Right Damaged	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Residual Traces of Repair	Repair
Door Front Left Dented	Repair
Door Front Right Dented	Repair
Door Rear Left Dented	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Cracked	Replace
Tyre Front Left Damaged	Replace
Bolt(s) / Nut(s) Front Wheel Left Missing	Replace
Bolt(s) / Nut(s) Front Wheel Right Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Right Missing	Replace
Belly plates Damaged	Replace
Traction control light on	Repair
Steering wheel is hard to turn	Repair
Warning light on	Repair
Front tyres size differs	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.2	3.3	-	
Rear	2.4	2.5	-	
Emergency / Parking	2.2	2.4	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/45R17	94W	Durun	L919	V	0125	0 mm
Front Right	225/50R17	98W	Annaite	An608	V	2723	3 mm
Rear Left	225/45R17	94W	Durun	L919	V	2325	3 mm
Rear Right	225/45R17	94Y	Windforce	Catchfors	V	3025	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WMWLV720502N88967

DEKRA

CONDITION REPORT

Report No:
2017324195
DATE
11/11/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	INTERMITTENT	930AA1	SUPPLY VOLTAGE: UNDERVOLTAGE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.SIGNS OF SPRAY WORK DONE ON SOME BODY PANELS

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WMWLV720502N88967

DEKRA

CONDITION REPORT

Report No:
2017324195
DATE
11/11/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WMWLV720502N88967

DEKRA

CONDITION REPORT

Report No:
2017324195
DATE
11/11/2026



INTERIOR (FRONT DRIVER DOOR)



Automatic



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WMWLV720502N88967

DEKRA

CONDITION REPORT

Report No:
2017324195
DATE
11/11/2026



ENGINE 1



ENGINE 2




CHASSIS



Oil cap



Expention bottle



LF TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WMWLV720502N88967

DEKRA

CONDITION REPORT

Report No:
2017324195
DATE
11/11/2026




RF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



Shock and brake report



Diagnostic Report page 1



Diagnostic Report page 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WMWLV720502N88967

DEKRA


CONDITION REPORT


Report No:
2017324195
DATE
11/11/2026


Diagnostic Report page 3


Diagnostic Report page 4


Diagnostic Report page 5


Diagnostic Report page 6


Diagnostic Report page 7


No spare wheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WMWLV720502N88967

DEKRA

CONDITION REPORT

Report No:
2017324195
DATE
11/11/2026



Water level



Bonnet



Windscreen



Seat Front Right



Door Front Right



Side Mirror Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WMWLV720502N88967

DEKRA

CONDITION REPORT

Report No:
2017324195
DATE
11/11/2026



Front Bumper



Door Front Left



Door Rear Left



Rear bumper



Rear bumper



Tyre Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WMWLV720502N88967

DEKRA

CONDITION REPORT

Report No:
2017324195
DATE
11/11/2026



Belly plates



Bolt(s) / Nut(s) Front Wheel Right



Bolt(s) / Nut(s) Front Wheel Left



Bolt(s) / Nut(s) Rear Wheel Left



Bolt(s) / Nut(s) Rear Wheel Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WMWLV720502N88967