DEKRA

CONDITION REPORT

Report No:
2017317734
DATE
27/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	27/10/2026		
Inspection Date	27/10/2026		

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	VOLKSWAGEN	Registration Number	JZ37NYGP
Model	CADDY MAXI P-VAN 2.0 TDI DSL [2016-2018]	Register Number	
VIN	WV1ZZZ2KZHX058213	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	30/11/2026
Color	WHITE	Power / Displacement	
Year Model	2017	Paint Finish	TWO COAT UNI
Km Reading	328,129 KM	Fuel	DIESEL
Cab / Body Type	PANEL VAN	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2KZHX058213

DEKRA

CONDITION REPORT

Report No:
2017317734
DATE
27/10/2026





Damage	Repair Way
Air cleaner Damaged	Replace
Air Conditioner Insufficient	Replace
Brake Light Centre Damaged	Replace
Headlight Left Defective	Repair
Headlight Right Defective	Repair
Seat Front Left Damaged	Repair
Interior Mirror Missing	Replace
Hood Lining Dirty	Repair
Door Panel Rear Left Missing	Replace
Door Panel Rear Right Missing	Replace
Boot Panel Right Damaged	Repair
Steering Wheel Trim Excessive Wear & Tear	Repair
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Paintwork • Dull	Repair
Front Fender Left Paintwork • Dull	Repair
Front Fender Right Paintwork • Dull	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Paintwork • Dull	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Paintwork • Discoloured	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Defective	Repair
Sill Panel Right Dented	Repair
Load Body Defective	Repair
Windscreen Chipped	Repair
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Tyre Front Left Torn / Cut	Replace
Chassis Dented	Repair
Sub Frame Dented	Repair
Belly plates Damaged	Repair
Gearbox Mountings Cracked	Repair
Gearbox Oil Sweat	Repair
Fuel Tank Sweat	Repair
Triangle Missing	Replace
Warning lights illuminated on dashboard	Repair
Interior fuse box cover missing	Replace
Loose wiring inside of vehicle	Replace
Rear left door does not open	Repair
Rear left door opening cable loose	Repair
Rear bumper missing	Replace
Repair work done on diesel filter housing	Replace
Rear left and right tyre sizes different	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2KZHX058213

DEKRA

CONDITION REPORT

Report No: 2017317734
DATE 27/10/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.73	3.97	-	
Rear	2.44	2.4	-	
Emergency / Parking	1.72	1.71	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/70 R15C	104S	Dunlop	Sp-Van	V	0522	3 mm
Front Right	195/70 R15C	104S	Dunlop	Sp-Sport	V	0522	3 mm
Rear Left	195/65 R15	91H	Falken	Ziex	V	3920	2 mm
Rear Right	195/70 R15C	104S	Dunlop	Sp-Van	V	0522	2 mm
Spare	195/65 R15	91V	Lanvigator	Comfort	V	0221	4 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	01-ENGINE CONTROL MODULE 1	P261A00	COOLANT PUMP 2,OPEN CIRCUIT	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Interior: Rear right door handle plastic cover missing.
Body • Exterior: Signs of branding on body panels.Poor residual traces of repair on body panels.Body panels misaligned.Stone chips and spray work on body panels.Dents and scratches on body panels.
Axle and Suspension: Front suspension faulty.
Undercarriage: Bottom of engine and gearbox fully covered.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks:

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2KZHX058213

DEKRA

CONDITION REPORT

Report No:
2017317734
DATE
27/10/2026

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2KZHX058213

DEKRA

CONDITION REPORT

Report No:
2017317734
DATE
27/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2KZHX058213

DEKRA

CONDITION REPORT

Report No:
2017317734
DATE
27/10/2026




90 DEGREE RIGHT



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



Oil cap and dipstick



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2KZHX058213

DEKRA

CONDITION REPORT

Report No:
2017317734
DATE
27/10/2026



Front chassis




Rear chassis




LF TYRE TREAD



LR TYRE TREAD



RF TYRE TREAD



RR TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2KZHX058213

DEKRA

CONDITION REPORT

Report No:
2017317734
DATE
27/10/2026



Brake and shock absorber repor




Loose wiring



Diagnostic report page 1



Diagnostic report page 2



Diagnostic report page 3



Spare wheel Accessories

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2KZHX058213

DEKRA

CONDITION REPORT

Report No:
2017317734
DATE
27/10/2026




Spare wheel



Rear left door opening cable



LICENSE DISC



VIN PLATE OR STICKER



Door Panel Rear Left



Door Panel Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2KZHX058213

DEKRA

CONDITION REPORT

Report No:
2017317734
DATE
27/10/2026



Steering Wheel Trim



Hood Lining



Front Fender Right



Side Mirror Right



Door Front Right



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2KZHX058213

DEKRA

CONDITION REPORT

Report No:
2017317734
DATE
27/10/2026



Door Rear Right



Seat Front Left



Seat Front Left



Brake Light Centre



Boot Panel Right



Load Body

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2KZHX058213

DEKRA

CONDITION REPORT

Report No:
2017317734
DATE
27/10/2026



Rear Fender Left



Door Rear Left



Side Mirror Left



Air Conditioner



Front Fender Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2KZHX058213

DEKRA

CONDITION REPORT

Report No:
2017317734
DATE
27/10/2026



Bonnet



Windscreen



Water level



Air cleaner



Control Arm Bush(es) Front Axle Right



Control Arm Bush(es) Front Axle Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2KZHX058213

DEKRA

CONDITION REPORT

Report No:
2017317734
DATE
27/10/2026



Front Bumper


Front Bumper


Front Bumper


Sill Panel Right


Belly plates


Tyre Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2KZHX058213

DEKRA

CONDITION REPORT

Report No:
2017317734
DATE
27/10/2026



Gearbox



Sub Frame



Gearbox Mountings



Chassis



Chassis



Belly plates

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2KZHX058213

DEKRA

CONDITION REPORT

Report No:
2017317734
DATE
27/10/2026



Fuel Tank



Headlight Left



Headlight Right



Water level



Interior Mirror

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2KZHX058213