DEKRA

# CONDITION REPORT

**Report No:**
**2017311215**
**DATE**
**13/10/2026**

*MFC Auction House*
*M57 Pretoria Rd, Glenmarais, KEMPTON PARK*
*Gauteng*

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572








## Assignment

| | | | |
|---|---|---|---|
| Client | MFC Auction House | Inspection Location | MFC<br>M57 Pretoria Road - 1619<br>Kempton Park - GT |
| Requested Date | 13/10/2026 | | |
| Inspection Date | 13/10/2026 | | |

## Vehicle Data

| | | | |
|---|---|---|---|
| Vehicle Type | PASSENGER VEHICLE | Registered Owner | |
| Manufacturer | VOLKSWAGEN | Registration Number | JY81TCGP |
| Model | T-CROSS 1.0 TSI 85KW HIGHLINE DSG [2019-2021] | Register Number | |
| | | Date Of First Licensing | |
| VIN | WVGZZZC1ZMY093066 | Last COR | |
| Engine Number | | License Expiry Date | 28/02/2027 |
| Doors | 5 | Power / Displacement | |
| Color | BLACK | Paint Finish | M - METALLIC |
| Year Model | 2021 | Fuel | PETROL |
| Km Reading | 79,666 KM | Transmission | AUTOMATIC |
| Cab / Body Type | HATCHBACK | | |

## Vehicle Options & Accessories

**Items**


## VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

# CONDITION REPORT

**Report No:**
**2017311215**
**DATE**
**13/10/2026**





| Damage | Repair Way |
|---|---|
| Door Front Right Paintwork • Scratched | Repair |
| Rear bumper Paintwork • Scratched | Repair |
| Steering Rack Boot Right Torn / Cut | Replace |
| Airbag warning light illuminated | Repair |

## Brakes

### Brake Test Results

| | Left | Right | | |
|---|---|---|---|---|
| | Braking Force [KN] | Braking Force [KN] | Axle Weight [KG] | Deceleration [m/s²] |
| **Front** | 3.6 | 3.8 | - | |
| **Rear** | 2.8 | 2.1 | - | |
| **Emergency / Parking** | 1.9 | 1.5 | - | |

## Tyres and Rims

### Tyre Specification & Measurement

| | Size | Load/Speed Index | Manufacture | Model | Type* | Production Date | Tread Depth (mm) |
|---|---|---|---|---|---|---|---|
| **Front Left** | 215/45R18 | 93Y | Bridgestone | Potenza | V | 0225 | 5 mm |
| **Front Right** | 215/45R18 | 93Y | Bridgestone | Potenza | V | 0225 | 3 mm |
| **Rear Left** | 215/45R18 | 93Y | Bridgestone | Potenza | V | 0225 | 5 mm |
| **Rear Right** | 215/45R18 | 93Y | Bridgestone | Potenza | V | 0225 | 5 mm |
| **Spare** | 205/55R16 | 91H | Giti | GitiSynergy | V | 0000 | 6 mm |

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZZC1ZMY093066

DEKRA

# CONDITION REPORT

**Report No:**
**2017311215**
**DATE**
**13/10/2026**

## Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System | Code | Description | Status |
|---|---|---|---|---|
| 1 | AIRBAG | B13BCF2 | MULTIPLE COLLISION BRAKE, NO FUNCTION | |

## Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

## Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.SIGNS OF SPRAY WORK DONE ON BODY PANELS / BOTTOM OF ENGINE IS FULLY COVERED / UNDERCARRIAGE IS FULLY COVERED

## Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

## Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZZC1ZMY093066

DEKRA

# CONDITION REPORT

**Report No:**
**2017311215**
**DATE**
**13/10/2026**



90 DEGREE FRONT



90 DEGREE REAR


FRONT RIGHT CORNER


REAR LEFT CORNER


90 DEGREE RIGHT


90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZZC1ZMY093066

DEKRA

# CONDITION REPORT

**Report No:**
**2017311215**
**DATE**
**13/10/2026**



INTERIOR (FRONT DRIVER DOOR)



Automatic transmission



DASHBOARD (W/ ENGINE RUNNING)




ODOMETER




LICENSE DISC




VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZZC1ZMY093066

DEKRA

# CONDITION REPORT

**Report No:**
**2017311215**
**DATE**
**13/10/2026**



ENGINE 1



ENGINE 2



REAR



CHASSIS



Oil cap and dipstick



Expansion bottle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZZC1ZMY093066

DEKRA

# CONDITION REPORT

**Report No:**
**2017311215**
**DATE**
**13/10/2026**



LF TYRE TREAD



RF TYRE TREAD




LR TYRE TREAD



RR TYRE TREAD




Sparewheel



Shock and brake report

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZZC1ZMY093066

DEKRA

# CONDITION REPORT


**Report No:**
**2017311215**
**DATE**
**13/10/2026**



Diagnostics report



Diagnostics report




Diagnostics report




Airbag warning lights illumina



Door Front Right



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZZC1ZMY093066

DEKRA

# CONDITION REPORT

**Report No:**
**2017311215**
**DATE**
**13/10/2026**



Water level



Steering Rack Boot Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZZC1ZMY093066