DEKRA

CONDITION REPORT

Report No:
2017316731
DATE
23/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	23/10/2026		
Inspection Date	23/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	VOLKSWAGEN	Registration Number	KR48KLGP
Model	POLO SEDAN 1.4 TRENDLINE [2020-2022]	Register Number	
VIN	WVWZZZ60ZMT119482	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	30/06/2027
Color	WHITE	Power / Displacement	
Year Model	2021	Paint Finish	TWO COAT UNI
Km Reading	365,265 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZ60ZMT119482

DEKRA

CONDITION REPORT

Report No: 2017316731
DATE 23/10/2026



Damage	Repair Way
Central Air Vent Damaged	Repair
Radio/CD/USB Defective	Repair
Headlight Left Damaged	Replace
Headlight Right Damaged	Replace
Seat Front Right Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
C • Pillar Right Damaged	Repair
Front Fender Left Damaged	Replace
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Roof Damaged	Repair
Tyre Front Left Worn	Replace
Tyre Rear Left Worn	Replace
Tyre Rear Right Worn	Replace
Radiator Cradle Damaged	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.63	2.68	-	
Rear	2.05	2.1	-	
Emergency / Parking	1.6	1.69	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	175/70R14	93S	Sumitomo	Radial	V	00000	0 mm
Front Right	175/70R14	84H	Sumitomo	Radial	V	4523	2 mm
Rear Left	175/70R14	84T	Anchee	Radial	V	2125	0 mm
Rear Right	175/70R14	84H	Sumitomo	Radial	V	2224	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZ60ZMT119482

DEKRA

CONDITION REPORT

Report No:
2017316731
DATE
23/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE CONTROL MODULE 1	P1570:00/05488:000	ENGINE CONTROL UNIT DISABLED	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Electrical Components and Instruments: radio does not play sound.
Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels. Repair work done to vehicle below standard.
Tyres and Rims: left front tire details not clearly visible. left front wheel sidewall damaged.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZ60ZMT119482


DEKRA

CONDITION REPORT


Report No:
2017316731
DATE
23/10/2026



Brake and shock absorber



ADDITIONAL 4



ADDITIONAL 5



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZ60ZMT119482

DEKRA

CONDITION REPORT

Report No:
2017316731
DATE
23/10/2026



DASHBOARD (W/ ENGINE RUNNING)

ODOMETER



Manual.



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZ60ZMT119482


DEKRA

CONDITION REPORT


Report No:
2017316731
DATE
23/10/2026



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZ60ZMT119482

DEKRA

CONDITION REPORT

Report No:
2017316731
DATE
23/10/2026



VIN PLATE OR STICKER



ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZ60ZMT119482

DEKRA

CONDITION REPORT

Report No:
2017316731
DATE
23/10/2026



Headlight Right



Headlight Left




Front Bumper



Front Bumper



Bonnet



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZ60ZMT119482


DEKRA

CONDITION REPORT

Report No:
2017316731
DATE
23/10/2026



Rear Fender Left



Door Front Left



Door Rear Left



Rear bumper



Rear bumper



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZ60ZMT119482

DEKRA

CONDITION REPORT

Report No:
2017316731
DATE
23/10/2026




Door Rear Right



Door Front Right



Front Fender Right



Rear Fender Right



C • Pillar Right



Roof

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZ60ZMT119482

DEKRA

CONDITION REPORT

Report No:
2017316731
DATE
23/10/2026



Seat Front Right



Radio/CD/USB



Central Air Vent



Central Air Vent



Central Air Vent



Tyre Rear Left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZ60ZMT119482


DEKRA

CONDITION REPORT

Report No:
2017316731
DATE
23/10/2026



Tyre Rear Right



Tyre Front Left



Radiator Cradle



Tyre Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZ60ZMT119482