CONDITION REPORT

Report No:
2017316062
DATE
22/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	22/10/2026		
Inspection Date	22/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	VOLKSWAGEN	Registration Number	MK20RJGP
Model	POLO SEDAN 1.6 MPI 81KW [2023-ON]	Register Number	
VIN	WVWZZZD2ZRT015215	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	30/04/2027
Color	SILVER	Power / Displacement	
Year Model	2023	Paint Finish	C - COMMON
Km Reading	125,475 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZD2ZRT015215

DEKRA

CONDITION REPORT

Report No:
2017316062
DATE
22/10/2026





Damage	Repair Way
Side Mirror Left Paintwork • Chipmarks	Repair
Side Mirror Right Paintwork • Chipmarks	Repair
Front Fender Right Dented	Repair
Door Front Right Dented	Repair
Door Rear Right Dented	Repair
Rear bumper Damaged	Repair
Gearbox Oil Sweat	Repair
Body Exterior	minor dents scratches stone chips

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.5	3.2	-	
Rear	2.1	2.3	-	
Emergency / Parking	1.9	2.2	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/55R16	91V	ROYAL BLACK	Royal Mile	V	4625	4 mm
Front Right	205/55R16	91V	ROYAL BLACK	Royal Mile	V	4425	4 mm
Rear Left	205/55R16	91V	CONTINENTAL	premium cont	V	4223	4 mm
Rear Right	205/55R16	91V	CONTINENTAL	contipremium	V	0524	4 mm
Spare	195/65R15	91H	MRF	ECOTRED	V	////	5 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZD2ZRT015215

DEKRA

CONDITION REPORT

Report No:
2017316062
DATE
22/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE CONTROL MODULE	U04160	INVALID DATA RECEIVED FROM VEHICLE DYNAMICS CONTRO	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: lower inner fender tray missing

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZD2ZRT015215

DEKRA

CONDITION REPORT

Report No:
2017316062
DATE
22/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZD2ZRT015215

DEKRA

CONDITION REPORT

Report No:
2017316062
DATE
22/10/2026



90 DEGREE RIGHT



Manual



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



oil cap and dipstick



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZD2ZRT015215

DEKRA

CONDITION REPORT

Report No:
2017316062
DATE
22/10/2026




ENGINE 2




CHASSIS



Chasis



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZD2ZRT015215

DEKRA

CONDITION REPORT

Report No:
2017316062
DATE
22/10/2026




RF TYRE TREAD



Sparewheel




VIN PLATE OR STICKER



Brake report



Diagnostics



LICENSE DISC


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZD2ZRT015215

DEKRA

CONDITION REPORT

Report No:
2017316062
DATE
22/10/2026



Diagnostics



Rear bumper



Rear bumper



Rear bumper



Front Fender Right



Side Mirror Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZD2ZRT015215

DEKRA

CONDITION REPORT

Report No:
2017316062
DATE
22/10/2026



Door Front Right



Door Rear Right



Gearbox



Water level



Side Mirror Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZD2ZRT015215