

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--
VIN: AAVZZZ6RZJU017982

Odometer Reading: 173489
License Plate: HR37RBGP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V19.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned(9)

System	Status/DTC
01 - Engine Control Module 1	1
03 - Brakes 1	1
09 - Electronic central electric	3
15 - Airbag	0
17 - Instrument cluster	0
19 - Gateway	1
25 - Anti-Theft Immobilizer	2
44 - Power Steering	1
56 - Radio	3

DTC (12)

01 - Engine Control Module 1 (1 DTC)

DTC	Description	Status
P1603:00/05 635:000	Ctrl. module faulty	Passive/Sporadic

03 - Brakes 1 (1 DTC)

DTC	Description	Status
U010000	Lost Communication with ECM/PCM	Passive/Sporadic

09 - Electronic central electric (3 DTCs)

DTC	Description	Status
01758:011	Lamps for brake lights - Open circuit	Passive/Sporadic
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic

00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
-----------	---	------------------

19 - Gateway (1 DTC)

DTC	Description	Status
01314:004	Engine control unit - No signal/communication	Passive/Sporadic

25 - Anti-Theft Immobilizer (2 DTCs)

DTC	Description	Status
B104A00	Engine control unit 1/power electronics 4 not authorized	Passive/Sporadic
B104C29	Key Range/performance	Passive/Sporadic

44 - Power Steering (1 DTC)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

56 - Radio (3 DTCs)

DTC	Description	Status
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic
01044:000	Control module incorrectly coded	Active/static

Technician Notes

2016372169

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.