

# Volkswagen VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Volkswagen/Polo Vivo/--  
 VIN: AAVZZZ6RZLU015307

Odometer Reading: 53843  
 License Plate: N > A

## Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
 Version: V19.50

Serial Number: VB8GJCC01509  
 Repair Order Number: --

## System Scanned( 9 )

System	Status/DTC
01 - Engine Control Module 1	 0
03 - Brakes 1	 0
09 - Electronic central electric	 3
15 - Airbag	 1
17 - Instrument cluster	 0
19 - Gateway	 0
25 - Anti-Theft Immobilizer	 1
44 - Power Steering	 1
56 - Radio	 1

## DTC ( 7 )

### 09 - Electronic central electric ( 3 DTCs )

DTC	Description	Status
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
01598:000	Drive battery voltage	Active/static

### 15 - Airbag ( 1 DTC )

DTC	Description	Status
B200000	Ctrl. module faulty	Passive/Sporadic

### 25 - Anti-Theft Immobilizer ( 1 DTC )

DTC	Description	Status
-----	-------------	--------

B104A00 Engine control unit 1/power electronics 4 not authorized Passive/Sporadic

**44 - Power Steering ( 1 DTC )**

DTC	Description	Status
U140A00	Terminal 30 Open circuit	Active/static

**56 - Radio ( 1 DTC )**

DTC	Description	Status
01044:000	Control module incorrectly coded	Active/static

**Technician Notes**

2016583632

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note:Please save a copy of this report for your records.