



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250414120347
Test Time: 2025-04-14 12:03:47
Technician: Werner

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--
VIN: AAVZZZ6RZPU002991

Odometer Reading: 76488
License Plate: KX33LXGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V22.00

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(9)

System	Status/DTC
01 - Engine Control Module 1	0
03 - Brakes 1	4
09 - Electronic central electric	5
15 - Airbag	1
17 - Instrument cluster	1
19 - Gateway	0
25 - Anti-Theft Immobilizer	1
44 - Power Steering	4
56 - Radio	2

DTC (18)

03 - Brakes 1 (4 DTCs)

DTC	Description	Status
U010000	Lost Communication with ECM/PCM	Passive/Sporadic
C106A16	ABS valves voltage supply Voltage too low	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic
U101400	Control module incorrectly coded	Passive/Sporadic

09 - Electronic central electric (5 DTCs)

DTC	Description	Status
03429:011	Activation of right cornering light - Open circuit	Active/static



00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
02604:000	Message 'Voltage supply too low' from Power Steering Control Module	Passive/Sporadic
03156:014	Anti-theft alarm system sensor - Faulty	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
U140000	Function restriction Caused by low voltage	Passive/Sporadic

17 - Instrument cluster (1 DTC)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

25 - Anti-Theft Immobilizer (1 DTC)

DTC	Description	Status
B104A00	Engine control unit 1/power electronics 4 not authorized	Passive/Sporadic

44 - Power Steering (4 DTCs)

DTC	Description	Status
U140000	Function restriction Caused by low voltage	Active/static
U140A00	Terminal 30 Open circuit	Active/static
U140A00	Terminal 30 Open circuit	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic

56 - Radio (2 DTCs)

DTC	Description	Status
02873:004	Rearview camera system control module - No signal/communication	Passive/Sporadic
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic

Technician Notes

2016842211

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.