



Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20231222112133
Test Time: 2023-12-22 11:21:33
Technician: Sbu

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AW/C1 - T-Cross 2019 >/--
VIN: AAVZZZAWZMU052716

Odometer Reading: 85192km
License Plate: N o n e r e g n u m b e r

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V19.00

Serial Number: VB8GJCC01482
Repair Order Number: --

System Scanned(16)

System	Status/DTC
01 - Engine Control Module 1	 3
02 - Transmission electronics	 0
03 - Brakes 1	 1
08 - Air Conditioning	 1
09 - Electronic central electric	 1
15 - Airbag	 0
17 - Instrument cluster	 2
19 - Gateway	 2
44 - Power Steering	 1
55 - Headlight Regulation	 1
5F - Information electronics 1	 2
76 - Parking assistance	 1
A9 - Structure-Borne Sound Actuator	 0
CA - Sunroof control module	 1
D6 - Light Control Left 2	 0
D7 - Light Control Right 2	 4

DTC (20)

01 - Engine Control Module 1 (3 DTCs)



DTC	Description	Status
P085000	Park/Neutral Switch Input Circuit	Passive/Sporadic
P310B00	Fuel low pressure regulation Fuel pressure out of range	Active/static
P125000	Fuel level too low	Active/static

03 - Brakes 1 (1 DTC)

DTC	Description	Status
C102D00	Tire pressure warning	Active/static

08 - Air Conditioning (1 DTC)

DTC	Description	Status
B10CD00	Function restriction caused by energy management	Passive/Sporadic

09 - Electronic central electric (1 DTC)

DTC	Description	Status
U112300	Databus error value received	Active/static

17 - Instrument cluster (2 DTCs)

DTC	Description	Status
U111000	Function restriction caused by communication interruption	Passive/Sporadic
U112100	Data bus message missing	Passive/Sporadic

19 - Gateway (2 DTCs)

DTC	Description	Status
U140600	Static current too high	Passive/Sporadic
B1802F1	NV-Energy management Alarm triggered	Passive/Sporadic

44 - Power Steering (1 DTC)

DTC	Description	Status
B200FF0	Internal malfunction	Passive/Sporadic

55 - Headlight Regulation (1 DTC)

DTC	Description	Status
C108000	Left-/right hand driving switch-over active	Active/static

5F - Information electronics 1 (2 DTCs)

DTC	Description	Status
B10CD00	Function restriction caused by energy management	Passive/Sporadic

B129B13	Microphone 1 Open circuit	Passive/Sporadic
---------	------------------------------	------------------

76 - Parking assistance (1 DTC)

DTC	Description	Status
B10F904	Right front center parking aid sensor Faulty	Active/static

CA - Sunroof control module (1 DTC)

DTC	Description	Status
U112200	Data bus message implausible	Passive/Sporadic

D7 - Light Control Right 2 (4 DTCs)

DTC	Description	Status
C11BD01	LED daytime running/park. light Electrical error	Active/static
C1199F6	Hi beam light bulb Overtemperature protection active	Passive/Sporadic
C1198F6	Low beam light bulb Overtemperature protection active	Passive/Sporadic
C11BDF1	LED daytime running/park. light Current coding implausible	Passive/Sporadic

Technician Notes

2016210736

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.