

Isuzu VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Isuzu/X-Rider/4JK1

VIN: ADMLREHR7F4779467

Odometer Reading: 318664

License Plate: KK01XPGP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Version: V5.43

Serial Number: VB8GJCC01509

Repair Order Number: --

System Scanned(5)

System	Status/DTC
ECM(Engine Control Module)	 1
ABS(Anti-lock Brake System)	 1
SRS(Supplemental Restraint System)	 2
IMMO(Immobilizer)	 1
SCD(Speedometer Control Device)	 0

DTC (5)

ECM(Engine Control Module) (1 DTC)

DTC	Description	Status
U0167	Lost communication with vehicle immobilizer control module	Not present

ABS(Anti-lock Brake System) (1 DTC)

DTC	Description	Status
C0710_4B	Steering angle sensor (SAS) center position invalid fault	Present

SRS(Supplemental Restraint System) (2 DTCs)

DTC	Description	Status
B1325_03	Battery voltage too low	Not present
B101D_30	ECU fault	Not present

IMMO(Immobilizer) (1 DTC)

DTC	Description	Status
B0003	Transponder key problem	Not present

Technician Notes

2016957017

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.