

# Ford VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Ford/Ranger / Mazda B-Series / Troller/--  
 VIN: AFAGXXMJ2GHU44411

Odometer Reading: 211942  
 License Plate: HNL879FS

## Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE














Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
 Version: V8.20

Serial Number: VB8GJCC01482  
 Repair Order Number: --

## System Scanned ( 12 )

System	Status/DTC
PCM (Powertrain Control Module)	 6
ABS (Anti-lock Brake System)	 0
RCM (Restraint Control Module)	 0
IPC (Instrument Panel Control Module)	 0
ACM (Audio Control Module)	 0
BdyCM(Body control module)	  1
FCIM (Front Controls Interface Module)	 0
GWM (Gateway Module A)	 0
PSCM (Power Steering Control Module)	 0
RTM (Radio Transceiver Module)	 0
SCCM (Steering Column Control Module)	 0
TRM (Trailer Module)	 0

## DTC ( 7 )

### PCM (Powertrain Control Module) ( 6 DTCs )

DTC	Description	Status
P0069:22-EC	MAP(Manifold absolute pressure sensor) - BP(Barometric pressure) Correlation	CMDTCs
P0313:68-28	Misfire Detected With Low Fuel	CMDTCs
P062F:00-2C	Internal Control Module EEPROM Error	CMDTCs

P115A:68-28	Low Fuel Level - Forced Limited Power	CMDTCs
P115B:68-28	Low Fuel Level - Forced Engine Shutdown	CMDTCs
P1933:68-28	Fuel Level Signal	CMDTCs

**BdyCM(Body control module) ( 1 DTC )**

DTC	Description	Status
B1D01:15-48	Right Low Beam	CMDTCs

**Technician Notes**

2016207091

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note:Please save a copy of this report for your records.