

Ford VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Ford/Ranger/--

VIN: AFAPXXMJ2PRR66156

Odometer Reading: 74901

License Plate: LV30TKGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT

Version: V9.31

Serial Number: VB8GJCC01509

Repair Order Number: --

 System Scanned (27)

System		Status/DTC
PCM(Powertrain control module)		 3
TCM(Transmission control module)		 1
ABS(Anti-lock brake system)		 1
RCM(Restraint control module)		 0
IPC(Instrument panel control module)		 5
ACM(Audio control module)		 0
APIM(Accessory protocol interface module)		 0
BCMC(Body control module C)		 0
BdyCM(Body control module)		 0
CCMii(Cruise control module)		 0
DDM(Driver front door module)		 0
DSP(Digital signal processing module (audio))		 0
FCIMB(Front controls interface module B)		 0
GSM(Gear shift module)		 0
GWM(Gateway module A)		 0
HVAC(Heating ventilation air conditioning)		 0
IPMA(Image processing module A)		 1
MRCMA(Movable roof control module A)		 3
PDM(Passenger front door module)		 0
PSCM(Power steering control module)		 1

RTM(Radio transceiver module)		✓ 0
SCCM(Steering column control module)		✗ 1
SODL(Side obstacle detection control module - left)	ADAS	✓ 0
SODR(Side obstacle detection control module - right)	ADAS	✓ 0
TCU(Telematic control unit)		✓ 0
TRM(Trailer module)		✓ 0
WACM(Wireless accessory charging module)		✓ 0

DTC (9)

ABS(Anti-lock brake system) (1 DTC)

DTC	Description	Status
U3003:16-68	Battery voltage	CMDTCs

IPC(Instrument panel control module) (5 DTCs)

DTC	Description	Status
U0159:00-08	Lost Communication With Parking Assist Control Module A	CMDTCs
U0232:00-08	Lost Communication With Side Obstacle Detection Control Module A	CMDTCs
U0233:00-08	Lost Communication With Side Obstacle Detection Control Module B	CMDTCs
U023A:00-08	Lost Communication With Image Processing Module A	CMDTCs
U3003:16-08	Battery voltage	CMDTCs

IPMA(Image processing module A) (1 DTC)

DTC	Description	Status
U0420:86-28	Invalid Data Received from Power Steering Control Module A	CMDTCs

PSCM(Power steering control module) (1 DTC)

DTC	Description	Status
U3003:68-28	Battery voltage	CMDTCs

SCCM(Steering column control module) (1 DTC)

DTC	Description	Status
U023A:08-28	Lost Communication With Image Processing Module A	CMDTCs

Technician Notes

2017294963

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.